



# North Michigan RC Lead Water Test Results



## FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011556	5/15/2018	5/15/2019	1	Cooler	In hallway adjacent to women's restroom Low Left	WF-05152018-011556	2/26/2019	FT-FY19-022019-011556-A	<1	FT-FY19-022019-011556-B	<1
WS- 011557	5/15/2018	5/15/2019	1	Cooler	In hallway adjacent to women's restroom High Right	WF-05152018-011557	2/26/2019	FT-FY19-022019-011557-A	<1	FT-FY19-022019-011557-B	<1
WS- 011558	5/15/2018	5/15/2019	1	Cooler	In hallway adjacent to room 104 High Left	WF-05152018-011558	2/26/2019	FT-FY19-022019-011558-A	<1	FT-FY19-022019-011558-B	<1
WS- 011559	5/15/2018	5/15/2019	1	Cooler	In hallway adjacent to room 104 Low Right	WF-05152018-011559	2/26/2019	FT-FY19-022019-011559-A	<1	FT-FY19-022019-011559-B	<1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011560	5/15/2018	5/15/2019	1	Food Prep Sink	In kitchenette 107 within activity room 108	WF-05152018-011560	2/26/2019	FT-FY19-022019-011560-A	<1	FT-FY19-022019-011560-B	<1
WS- 011561	2/21/2019	2/21/2020	1	Food Prep Sink	In main kitchen within the community room	WF-02212019-011561	2/26/2019	FT-FY19-022019-011561-A	<1	FT-FY19-022019-011561-B	<1