



# NOYES EC LEAD WATER TEST RESULTS



	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)
1	NOYES EDUCATIONAL CAMPUS	WS- 004054	8/18/2016	1	Health Suite	In health suite 103	FT-82016-004054-A	< 1	FT-82016-004054-B	< 1
2	NOYES EDUCATIONAL CAMPUS	WS- 004061	8/18/2016	1	Cooler	In hallway across from room 108 Low Left	FT-82016-004061-A	< 1	FT-82016-004061-B	< 1
3	NOYES EDUCATIONAL CAMPUS	WS- 004062	8/18/2016	1	Cooler	In hallway across from room 108 High Right	FT-82016-004062-A	< 1	FT-82016-004062-B	< 1
4	NOYES EDUCATIONAL CAMPUS	WS- 004074	8/18/2016	1	Cooler	In hallway across from room 121 Low Left	FT-82016-004074-A	< 1	FT-82016-004074-B	< 1
5	NOYES EDUCATIONAL CAMPUS	WS- 004075	8/18/2016	1	Cooler	In hallway across from room 121 High Right	FT-82016-004075-A	< 1	FT-82016-004075-B	< 1
6	NOYES EDUCATIONAL CAMPUS	WS- 004077	8/18/2016	1	Food Prep Sink	In kitchen Left	FT-82016-004077-A	< 1	FT-82016-004077-B	< 1
7	NOYES EDUCATIONAL CAMPUS	WS- 004080	8/18/2016	1	Fountain	In classroom 112 Right	FT-82016-004080-A	< 1	FT-82016-004080-B	< 1
8	NOYES EDUCATIONAL CAMPUS	WS- 004081	8/18/2016	1	Cooler	In hallway adjacent to room 116 Low Left	FT-82016-004081-A	< 1	FT-82016-004081-B	< 1
9	NOYES EDUCATIONAL CAMPUS	WS- 004082	8/18/2016	1	Cooler	In hallway adjacent to room 116 High Right	FT-82016-004082-A	< 1	FT-82016-004082-B	< 1
10	NOYES EDUCATIONAL CAMPUS	WS- 004084	8/18/2016	1	Fountain	In classroom 128	FT-82016-004084-A	< 1	FT-82016-004084-B	< 1
11	NOYES EDUCATIONAL CAMPUS	WS- 004086	8/18/2016	1	Fountain	In classroom 130	FT-82016-004086-A	< 1	FT-82016-004086-B	< 1
12	NOYES EDUCATIONAL CAMPUS	WS- 004088	8/18/2016	1	Fountain	In classroom 129	FT-82016-004088-A	< 1	FT-82016-004088-B	< 1
13	NOYES EDUCATIONAL CAMPUS	WS- 004090	8/18/2016	1	Fountain	In classroom 131	FT-82016-004090-A	< 1	FT-82016-004090-B	< 1
14	NOYES EDUCATIONAL CAMPUS	WS- 004092	8/18/2016	1	Fountain	In classroom 135	FT-82016-004092-A	< 1	FT-82016-004092-B	< 1
15	NOYES EDUCATIONAL CAMPUS	WS- 004094	8/18/2016	1	Fountain	In classroom 132	FT-82016-004094-A	< 1	FT-82016-004094-B	< 1
16	NOYES EDUCATIONAL CAMPUS	WS- 004096	8/18/2016	1	Fountain	In classroom 133	FT-82016-004096-A	< 1	FT-82016-004096-B	< 1
17	NOYES EDUCATIONAL CAMPUS	WS- 004098	8/18/2016	1	Fountain	In classroom 134	FT-82016-004098-A	< 1	FT-82016-004098-B	< 1
18	NOYES EDUCATIONAL CAMPUS	WS- 004099	8/18/2016	2	Cooler	In hallway adjacent to room 202 Low Left	FT-82016-004099-A	< 1	FT-82016-004099-B	< 1
19	NOYES EDUCATIONAL CAMPUS	WS- 004100	8/18/2016	2	Cooler	In hallway adjacent to room 202 High Right	FT-82016-004100-A	< 1	FT-82016-004100-B	< 1
20	NOYES EDUCATIONAL CAMPUS	WS- 004101	8/18/2016	2	Fountain	In classroom 203	FT-82016-004101-A	< 1	FT-82016-004101-B	< 1
21	NOYES EDUCATIONAL CAMPUS	WS- 004104	8/18/2016	2	Fountain	In classroom 205	FT-82016-004104-A	< 1	FT-82016-004104-B	< 1
22	NOYES EDUCATIONAL CAMPUS	WS- 004106	8/18/2016	2	Fountain	In classroom 204	FT-82016-004106-A	< 1	FT-82016-004106-B	< 1
23	NOYES EDUCATIONAL CAMPUS	WS- 004107	8/18/2016	2	Fountain	In classroom 206	FT-82016-004107-A	< 1	FT-82016-004107-B	< 1
24	NOYES EDUCATIONAL CAMPUS	WS- 004111	8/18/2016	2	Cooler	In hallway adjacent to stairwell A Low Left	FT-82016-004111-A	< 1	FT-82016-004111-B	< 1
25	NOYES EDUCATIONAL CAMPUS	WS- 004112	8/18/2016	2	Cooler	In hallway adjacent to stairwell A High Right	FT-82016-004112-A	< 1	FT-82016-004112-B	< 1
26	NOYES EDUCATIONAL CAMPUS	WS- 004114	8/18/2016	2	Fountain	In speech room 212	FT-82016-004114-A	< 1	FT-82016-004114-B	< 1
27	NOYES EDUCATIONAL CAMPUS	WS- 004116	8/18/2016	2	Fountain	In classroom 213	FT-82016-004116-A	< 1	FT-82016-004116-B	< 1
28	NOYES EDUCATIONAL CAMPUS	WS- 004118	8/18/2016	2	Fountain	In classroom 214	FT-82016-004118-A	< 1	FT-82016-004118-B	< 1
29	NOYES EDUCATIONAL CAMPUS	WS- 004120	8/18/2016	2	Fountain	In classroom 216	FT-82016-004120-A	< 1	FT-82016-004120-B	< 1