



Old Banneker Swing Space Lead in Water Test Results

FY23 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011900	4/13/2022	4/13/2023	Basement	Cooler	In cafeteria adjacent to kitchen area	WF-04132022-011900	9/2/2022	FT-FY23-08242022-011900-A	<1	FT-FY23-08242022-011900-B	<1
WS- 011929	4/13/2022	4/13/2023	1	Cooler	In hallway adjacent to room 102	WF-04132022-011929	9/2/2022	FT-FY23-08242022-011929-A	<1	FT-FY23-08242022-011929-B	<1
WS- 012040	4/13/2022	4/13/2023	2	Bottle Filler	In hallway adjacent to stairwell 6	WF-04132022-012040	9/2/2022	FT-FY23-08242022-012040-A	<1	FT-FY23-08242022-012040-B	<1
WS- 012041	4/13/2022	4/13/2023	2	Cooler	In hallway adjacent to stairwell 6	WF-04132022-012041	9/2/2022	FT-FY23-08242022-012041-A	<1	FT-FY23-08242022-012041-B	<1
WS- 012042	4/13/2022	4/13/2023	2	Bottle Filler	In hallway adjacent to stairwell 1	WF-04132022-012042	9/2/2022	FT-FY23-08242022-012042-A	<1	FT-FY23-08242022-012042-B	<1
WS- 012043	4/13/2022	4/13/2023	2	Cooler	In hallway adjacent to stairwell 1	WF-04132022-012043	9/2/2022	FT-FY23-08242022-012043-A	<1	FT-FY23-08242022-012043-B	<1
WS- 012499	4/13/2022	4/13/2023	2	Cooler	In hallway across from stairwell 4	WF-04132022-012499	9/2/2022	FT-FY23-08242022-012499-A	<1	FT-FY23-08242022-012499-B	<1
WS- 012503	4/13/2022	4/13/2023	3	Cooler	In hallway adjacent to room 305	WF-04132022-012503	9/2/2022	FT-FY23-08242022-012503-A	<1	FT-FY23-08242022-012503-B	<1
WS- 012505	4/13/2022	4/13/2023	3	Cooler	In hallway across from stairwell 3	WF-04132022-012505	9/2/2022	FT-FY23-08242022-012505-A	<1	FT-FY23-08242022-012505-B	<1
WS- 012602	8/24/2022	8/24/2023	Basement	Combo Fountain	In classroom 020B	WF-08242022-012602	9/2/2022	FT-FY23-08242022-012602-A	<1	FT-FY23-08242022-012602-B	<1
WS- 012604	8/24/2022	8/24/2023	Basement	Combo Fountain	In classroom 020A	WF-08242022-012604	9/2/2022	FT-FY23-08242022-012604-A	<1	FT-FY23-08242022-012604-B	<1
WS- 012606	8/24/2022	8/24/2023	Basement	Combo Fountain	In classroom 023	WF-08242022-012606	9/2/2022	FT-FY23-08242022-012606-A	<1	FT-FY23-08242022-012606-B	<1
WS- 012608	8/24/2022	8/24/2023	Basement	Combo Fountain	In classroom 09A	WF-08242022-012608	9/2/2022	FT-FY23-08242022-012608-A	<1	FT-FY23-08242022-012608-B	<1
WS- 012610	8/24/2022	8/24/2023	Basement	Combo Fountain	In classroom 09B	WF-08242022-012610	9/2/2022	FT-FY23-08242022-012610-A	<1	FT-FY23-08242022-012610-B	<1
WS- 012612	8/24/2022	8/24/2023	Basement	Combo Fountain	In classroom 05B	WF-08242022-012612	9/2/2022	FT-FY23-08242022-012612-A	2.2	FT-FY23-08242022-012612-B	<1
WS- 012614	8/24/2022	8/24/2023	Basement	Combo Fountain	In classroom 05A	WF-08242022-012614	9/2/2022	FT-FY23-08242022-012614-A	<1	FT-FY23-08242022-012614-B	<1
WS- 012618	8/24/2022	8/24/2023	Basement	Combo Fountain	In test kitchen 010 along wall	WF-08242022-012618	9/2/2022	FT-FY23-08242022-012618-A	<1	FT-FY23-08242022-012618-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011902	1/14/2022	1/14/2023	Basement	Food Prep Sink	In kitchen first clockwise from cafeteria entry door	WF-01142022-011902	9/2/2022	FT-FY23-08242022-011902-A	1.4	FT-FY23-08242022-011902-B	<1
WS- 012615	8/24/2022	8/24/2023	Basement	Food Prep Sink	In test kitchen 010 on island Left	WF-08242022-012615	9/2/2022	FT-FY23-08242022-012615-A	<1	FT-FY23-08242022-012615-B	<1
WS- 012616	8/24/2022	8/24/2023	Basement	Food Prep Sink	In test kitchen 010 on island Right	WF-08242022-012616	9/2/2022	FT-FY23-08242022-012616-A	<1	FT-FY23-08242022-012616-B	<1
WS- 012617	8/24/2022	8/24/2023	Basement	Food Prep Sink	In test kitchen 010 along wall	WF-08242022-012617	9/2/2022	FT-FY23-08242022-012617-A	<1	FT-FY23-08242022-012617-B	<1

FY23 Filter Test

Greater than 5ppb - Devices requiring remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012500	4/13/2022	4/13/2023	2	Break Room	In staff lounge	WF-04132022-012500	9/2/2022	FT-FY23-08242022-012500-A	<1	FT-FY23-08242022-012500-B	17.1

**First Re-Test (After Plumbing Check)
FY23 Filter Test**

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012500	9/6/2022	9/6/2023	2	Break Room	In staff lounge	WF-09062022-012500	9/13/2022	FT-FY23-09082022-012500-A	<1	FT-FY23-09082022-012500-B	<1