



ORR LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009808	Utility	Basement	In boiler room (water source)	WT-042916-9825- A	< 1	WT-042916-9825- B	1.3				
2 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009809	Kitchen	1	In kitchen	WT-042916-9826- A	< 1	WT-042916-9826- B	< 1				
3 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009810	Cooler	1	In all purpose room first clockwise from elevator	WT-042916-9827- A	< 1	WT-042916-9827- B	< 1				
4 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009811	Cooler	1	In all purpose room second clockwise from elevator	WT-042916-9828- A	< 1	WT-042916-9828- B	< 1				
5 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009812	Cooler	1	In all purpose room third clockwise from elevator	WT-042916-9829- A	< 1	WT-042916-9829- B	< 1				
6 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009813	Cooler	1	In hallway across from the main security desk	WT-042916-9830- A	< 1	WT-042916-9830- B	< 1				
7 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009814	Cooler	1	In hallway across from General office	WT-042916-9831- A	< 1	WT-042916-9831- B	< 1				
8 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009815	Cooler	1	In health suite	WT-042916-9832- A	< 1	WT-042916-9832- B	< 1				
9 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009816	Cooler	1	In hallway adjacent to teachers lounge	WT-042916-9833- A	< 1	WT-042916-9833- B	< 1				
10 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009817	Classroom	1	In room pre-k 3 on south wall Right	WT-042916-9834- A	< 1	WT-042916-9834- B	< 1				
11 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009818	Classroom	1	In room pre-k 3 on south wall Left	WT-042916-9835- A	< 1	WT-042916-9835- B	< 1				
12 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009819	Classroom	1	In pre-k 3 on south wall Right	WT-042916-9836- A	1.7	WT-042916-9836- B	< 1				
13 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009820	Cooler	1	In pre-k 3 on south wall	WT-042916-9837- A	< 1	WT-042916-9837- B	< 1				
14 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009821	Classroom	1	In pre-k 3 north wall Right	WT-042916-9838- A	2.3	WT-042916-9838- B	< 1				
15 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009822	Classroom	1	In pre-k 3 north wall Left	WT-042916-9839- A	< 1	WT-042916-9839- B	< 1				
16 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009823	Cooler	1	In pre-k 3 room north wall	WT-042916-9840- A	< 1	WT-042916-9840- B	< 1				
17 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009824	Classroom	1	In pre-k 3 souther section on south wall Right	WT-042916-9841- A	< 1	WT-042916-9841- B	< 1				
18 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009825	Classroom	1	In pre-k 3 southern section on south wall Left	WT-042916-9842- A	< 1	WT-042916-9842- B	< 1				
19 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009826	Cooler	1	In pre-k 3 southen section on south wall	WT-042916-9843- A	< 1	WT-042916-9843- B	< 1				
20 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009827	Classroom	1	In southern section of pre-k 3 on north wall	WT-042916-9844- A	2.9	WT-042916-9844- B	< 1				
21 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009828	Cooler	1	In pre-k 3 in the south section on north wall Left	WT-042916-9845- A	< 1	WT-042916-9845- B	< 1				
22 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009829	Classroom	1	In pre-k 3 in the south section on north wall Right	WT-042916-9846- A	< 1	WT-042916-9846- B	< 1				
23 ORR ELEMENTARY SCHOOL	5/11/2016	WS- 009830	Classroom	1	In kindergarten room south section Left	WT-042916-9847- A	1.5	WT-042916-9847- B	< 1				
24 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009831	Cooler	2	In hallway adjacent to girls restroom	WT-042916-9848- A	< 1	WT-042916-9848- B	< 1				
25 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009832	Classroom	2	In kindergarten on east wall Left	WT-042916-9849- A	< 1	WT-042916-9849- B	< 1				
26 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009833	Classroom	2	In kindergarten eastern section on east wall Right	WT-042916-9850- A	< 1	WT-042916-9850- B	< 1				
27 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009834	Classroom	2	In kindergarten eastern section on west wall Left	WT-042916-9851- A	7.2	WT-042916-9851- B	< 1				
28 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009835	Classroom	2	In kindergarten southern section on west wall Right	WT-042916-9852- A	1.6	WT-042916-9852- B	< 1				
29 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009836	Cooler	2	In hallway adjacent to boys restroom	WT-042916-9853- A	< 1	WT-042916-9853- B	< 1				
30 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009837	Cooler	3	In hallway adjacent to girls restroom	WT-042916-9854- A	< 1	WT-042916-9854- B	3.1				
31 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009838	Classroom	3	In eastern section grade 4 east wall Right	WT-042916-9855- A	9.8	WT-042916-9855- B	< 1				
32 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009839	Classroom	3	In eastern section grade 4 on east wall Left	WT-042916-9856- A	1.6	WT-042916-9856- B	< 1				
33 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009840	Classroom	3	In grade 4 east section on west wall Left	WT-042916-9857- A	2.4	WT-042916-9857- B	1.9				
34 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009841	Classroom	3	In grade 4 on east wall Right	WT-042916-9858- A	1.8	WT-042916-9858- B	< 1				
35 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009842	Cooler	3	In hallway adjacent to boys restroom	WT-042916-9859- A	< 1	WT-042916-9859- B	< 1				
36 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009843	Cooler	4	In hallway adjacent to girls restroom	WT-042916-9860- A	< 1	WT-042916-9860- B	< 1				
37 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009844	Classroom	4	In grade 5 west section on east wall Left	WT-042916-9861- A	< 1	WT-042916-9861- B	< 1				
38 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009845	Classroom	4	In grade 5 west section on east wall Right	WT-042916-9862- A	1.2	WT-042916-9862- B	< 1				
39 ORR ELEMENTARY SCHOOL	5/10/2016	WS- 009846	Cooler	4	In hallway adjacent to boy's restroom	WT-042916-9863- A	< 1	WT-042916-9863- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.