



Oxon Run Pool Lead Water Test Results



FY18 Filter Test

| Greater than 5 ppb - Devices Requiring Remediation | | | | | | | | | | | |
|--|-----------------------|-------------------|--------------|--------------|-----------------------------------|--------------------|---------------|------------------------|----------------------------------|------------------------|----------------------------------|
| RECORD ID | Filter Installed Date | Filter Expiration | Floor | Device Type | Device Location | WATER FILTERS Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
| WS- 006414 | 06/17/17 | 06/17/18 | Ground Floor | Health Suite | In health suite in first aid room | WF-62017-006414 | 6/6/18 | FT-FY18-62017-006414-A | 140 | FT-FY18-62017-006414-B | <1 |

First Re-Test (After Plumbing Check)

FY18 Filter Test

| Less than 5 ppb - Devices Requiring No Remediation | | | | | | | | | | | |
|--|-----------------------|------------------------|--------------|--------------|-----------------------------------|--------------------|---------------|-------------------------|----------------------------------|-------------------------|----------------------------------|
| RECORD ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | WATER FILTERS Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
| WS- 006414 | 06/07/18 | 06/07/19 | Ground Floor | Health Suite | In health suite in first aid room | WF-672018-006414 | 6/12/18 | FT-FY18-672018-006414-A | <1 | FT-FY18-672018-006414-B | <1 |