



OXON RUN REC LEAD WATER TEST RESULTS

May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	OXON RUN RECREATION CENTER	5/27/2016	WS- 006410	Other	Ground Floor	In passage in to men's locker (water Source)	WT-042916-6427- A	1.1	WT-042916-6427- B	< 1				
2	OXON RUN RECREATION CENTER	5/27/2016	WS- 006411	Other	Ground Floor	In men's locker room on north wall (sink) Left	WT-042916-6428- A	< 1	WT-042916-6428- B	< 1				
3	OXON RUN RECREATION CENTER	5/27/2016	WS- 006412	Other	Ground Floor	In men's locker room on north wall (sink) Mid	WT-042916-6429- A	< 1	WT-042916-6429- B	< 1				
4	OXON RUN RECREATION CENTER	5/27/2016	WS- 006413	Other	Ground Floor	In men's locker room on north wall (sink) Right	WT-042916-6430- A	< 1	WT-042916-6430- B	< 1				
5	OXON RUN RECREATION CENTER	5/27/2016	WS- 006414	Other	Ground Floor	In first aid room	WT-042916-6431- A	8.3	WT-042916-6431- B	< 1				
6	OXON RUN RECREATION CENTER	5/28/2016	WS- 006415	Other	Ground Floor	In women's locker room west wall (Sink) Left	WT-042916-6432- A	< 1	WT-042916-6432- B	< 1				
7	OXON RUN RECREATION CENTER	5/27/2016	WS- 006416	Other	Ground Floor	In women's locker room west wall (sink) Mid	WT-042916-6433- A	< 1	WT-042916-6433- B	1				
8	OXON RUN RECREATION CENTER	5/27/2016	WS- 006417	Other	Ground Floor	In women's locker room west wall (sink) Right	WT-042916-6434- A	< 1	WT-042916-6434- B	< 1				
9	OXON RUN RECREATION CENTER	5/27/2016	WS- 006418	Fountain	Ground Floor	In pool area on wall adjacent to the men's locker room on south wall	WT-042916-6435- A	< 1	WT-042916-6435- B	< 1				
10	OXON RUN RECREATION CENTER	5/27/2016	WS- 006419	Fountain	Ground Floor	In north play ground	WT-042916-6436- A	< 1	WT-042916-6436- B	< 1				
11	OXON RUN RECREATION CENTER	5/27/2016	WS- 006420	Fountain	Ground Floor	In play ground north	WT-042916-6437- A	< 1	WT-042916-6437- B	< 1				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.