



# OYSTER ADAMS (ADAMS) LEAD WATER TEST RESULTS May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	OYSTER ADAMS EDUCATIONAL CAMPUS	5/10/2016	WS- 003969	Utility	Basement	In boiler room	WT-042916-3986- A	1.4	WT-042916-3986- B	1.8				
2	OYSTER ADAMS EDUCATIONAL CAMPUS (ADAMS)	5/10/2016	WS- 003970	Cooler	1	In hallway adjacent to room 102	WT-042916-3987- A	< 1	WT-042916-3987- B	< 1				
3	OYSTER ADAMS EDUCATIONAL CAMPUS (ADAMS)	5/10/2016	WS- 003971	Classroom	1	In classroom 101	WT-042916-3988- A	4.3	WT-042916-3988- B	4				
4	OYSTER ADAMS EDUCATIONAL CAMPUS (ADAMS)	5/10/2016	WS- 003972	Classroom	1	In classroom 112	WT-042916-3989- A	6.7	WT-042916-3989- B	56	Filter will be installed and then retested			
5	OYSTER ADAMS EDUCATIONAL CAMPUS (ADAMS)	5/10/2016	WS- 003973	Health Suite	1	In health suite Mid	WT-042916-3990- A	8.6	WT-042916-3990- B	4.5				
6	OYSTER ADAMS EDUCATIONAL CAMPUS (ADAMS)	5/10/2016	WS- 003974	Health Suite	1	In health suite Right	WT-042916-3991- A	17.2	WT-042916-3991- B	30.9	Filter will be installed and then retested			
7	OYSTER ADAMS EDUCATIONAL CAMPUS (ADAMS)	5/10/2016	WS- 003975	Health Suite	1	In health suite Left	WT-042916-3992- A	1	WT-042916-3992- B	< 1				
8	OYSTER ADAMS EDUCATIONAL CAMPUS (ADAMS)	5/10/2016	WS- 003976	Cooler	1	In cafeteria	WT-042916-3993- A	1.4	WT-042916-3993- B	< 1				
9	OYSTER ADAMS EDUCATIONAL CAMPUS (ADAMS)	5/10/2016	WS- 003977	Kitchen	1	In kitchen	WT-042916-3994- A	< 1	WT-042916-3994- B	< 1				
10	OYSTER ADAMS EDUCATIONAL CAMPUS (ADAMS)	5/10/2016	WS- 003978	Cooler	1	In hallway adjacent to room 103	WT-042916-3995- A	1	WT-042916-3995- B	< 1				
11	OYSTER ADAMS EDUCATIONAL CAMPUS (ADAMS)	5/10/2016	WS- 003979	Classroom	1	In classroom 110	WT-042916-3996- A	< 1	WT-042916-3996- B	< 1				
12	OYSTER ADAMS EDUCATIONAL CAMPUS (ADAMS)	5/10/2016	WS- 003980	Break Room	1	In teacher's lounge	WT-042916-3997- A	< 1	WT-042916-3997- B	1.9				
13	OYSTER ADAMS EDUCATIONAL CAMPUS (ADAMS)	5/10/2016	WS- 003981	Break Room	2	In teacher's room	WT-042916-3998- A	< 1	WT-042916-3998- B	< 1				
14	OYSTER ADAMS EDUCATIONAL CAMPUS (ADAMS)	5/10/2016	WS- 003982	Fountain	2	In the gym	WT-042916-3999- A	1.6	WT-042916-3999- B	< 1				
15	OYSTER ADAMS EDUCATIONAL CAMPUS (ADAMS)	5/10/2016	WS- 003983	Fountain	2	In the gym	WT-042916-4000- A	< 1	WT-042916-4000- B	< 1				
16	OYSTER ADAMS EDUCATIONAL CAMPUS (ADAMS)	5/10/2016	WS- 003984	Cooler	2	In hallway adjacent to room 201	WT-042916-4001- A	< 1	WT-042916-4001- B	< 1				
17	OYSTER ADAMS EDUCATIONAL CAMPUS (ADAMS)	5/10/2016	WS- 003985	Cooler	2	In hallway adjacent to room 202	WT-042916-4002- A	< 1	WT-042916-4002- B	< 1				
18	OYSTER ADAMS EDUCATIONAL CAMPUS (ADAMS)	5/10/2016	WS- 003986	Cooler	3	In hallway adjacent to room 302	WT-042916-4003- A	< 1	WT-042916-4003- B	< 1				
19	OYSTER ADAMS EDUCATIONAL CAMPUS (ADAMS)	5/10/2016	WS- 003987	Cooler	3	In hallway adjacent to room 308	WT-042916-4004- A	< 1	WT-042916-4004- B	< 1				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.