



Oyster Adams MS Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 003970	3/28/2018	3/28/2019	1	Cooler	In hallway adjacent to room 102	WF-03282018-003970	12/15/2018	FT-FY19-122018-003970-A	<1	FT-FY19-122018-003970-B	<1	
WS- 003973	3/28/2018	3/28/2019	1	Health Suite	In health suite	Mid	WF-03282018-003973	12/15/2018	FT-FY19-122018-003973-A	<1	FT-FY19-122018-003973-B	<1
WS- 003974	3/28/2018	3/28/2019	1	Health Suite	In health suite	Right	WF-03282018-003974	12/15/2018	FT-FY19-122018-003974-A	<1	FT-FY19-122018-003974-B	<1
WS- 003975	3/28/2018	3/28/2019	1	Health Suite	In health suite	Left	WF-03282018-003975	12/15/2018	FT-FY19-122018-003975-A	<1	FT-FY19-122018-003975-B	<1
WS- 003976	3/28/2018	3/28/2019	1	Fountain	In cafeteria		WF-03282018-003976	12/15/2018	FT-FY19-122018-003976-A	<1	FT-FY19-122018-003976-B	<1
WS- 003978	3/28/2018	3/28/2019	1	Cooler	In hallway adjacent to room 103		WF-03282018-003978	12/15/2018	FT-FY19-122018-003978-A	<1	FT-FY19-122018-003978-B	<1
WS- 003980	3/28/2018	3/28/2019	1	Break Room	In staff lounge		WF-03282018-003980	12/15/2018	FT-FY19-122018-003980-A	<1	FT-FY19-122018-003980-B	<1
WS- 003981	3/28/2018	3/28/2019	2	Break Room	In staff lounge 209		WF-03282018-003981	12/15/2018	FT-FY19-122018-003981-A	<1	FT-FY19-122018-003981-B	<1
WS- 003982	3/28/2018	3/28/2019	2	Fountain	In gym on south wall		WF-03282018-003982	12/15/2018	FT-FY19-122018-003982-A	<1	FT-FY19-122018-003982-B	<1
WS- 003983	12/11/2018	12/11/2019	2	Fountain	In gym on north wall		WF-12112018-003983	12/15/2018	FT-FY19-122018-003983-A	<1	FT-FY19-122018-003983-B	<1
WS- 003984	12/11/2018	12/11/2019	2	Cooler	In hallway adjacent to room 201		WF-12112018-003984	12/15/2018	FT-FY19-122018-003984-A	<1	FT-FY19-122018-003984-B	<1
WS- 003985	3/28/2018	3/28/2019	2	Cooler	In hallway adjacent to room 202		WF-03282018-003985	12/15/2018	FT-FY19-122018-003985-A	<1	FT-FY19-122018-003985-B	<1
WS- 003986	3/28/2018	3/28/2019	3	Cooler	In hallway adjacent to room 302		WF-03282018-003986	12/15/2018	FT-FY19-122018-003986-A	<1	FT-FY19-122018-003986-B	<1
WS- 003987	3/28/2018	3/28/2019	3	Cooler	In hallway adjacent to room 308		WF-03282018-003987	12/15/2018	FT-FY19-122018-003987-A	<1	FT-FY19-122018-003987-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)			
WS- 003977	1	Food Prep Sink	In kitchen	12/15/2018	FT-FY19-122018-003977-A	<1	FT-FY19-122018-003977-B	<1			