

Palisades CC Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		er's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 004276	7/18/2018	7/18/2019	Ground Floor	Bottle Filler	In hallway next to boys and girls restroom	WF-071820	018-004276	2/12/2019	FT-FY19-022019-004276-A	<1	FT-FY19-022019-004276-B	<1
WS- 004277	7/18/2018	7/18/2019	Ground Floor	Cooler	In hallway next to boys and girls restroom High Le	ft WF-071820	018-004277	2/12/2019	FT-FY19-022019-004277-A	<1	FT-FY19-022019-004277-B	<1
WS- 004278	7/18/2018	7/18/2019	Ground Floor	Cooler	In hallway next to boys and girls restroom Low Rig	ht WF-071820	018-004278	2/12/2019	FT-FY19-022019-004278-A	<1	FT-FY19-022019-004278-B	<1
WS- 004280	7/20/2018	7/20/2019	Ground Floor	Break Room	In break room	WF-072020	018-004280	2/12/2019	FT-FY19-022019-004280-A	<1	FT-FY19-022019-004280-B	<1

Food Prep Sink

	Less than 5ppb - Devices requiring no remediation										
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 004279	7/18/2018	7/18/2019	Ground Floor	Food Prep Sink	In kitchen	WF-07182018-004279	2/12/2019	FT-FY19-022019-004279-A	<1	FT-FY19-022019-004279-B	<1