Palisades CC Lead in Water Test Results

FY20 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 004276	5/8/2019	5/8/2020	Ground Floor	Bottle Filler	In hallway next to boys and girls restroom	WF-05082019-004276	2/12/2020	FT-FY20-012020-004276-A	<1	FT-FY20-012020-004276-B	<1
WS- 004277	5/8/2019	5/8/2020	Ground Floor	Cooler	In hallway next to boys and girls restroom High Left	WF-05082019-004277	2/12/2020	FT-FY20-012020-004277-A	<1	FT-FY20-012020-004277-B	<1
WS- 004278	5/8/2019	5/8/2020	Ground Floor	Cooler	In hallway next to boys and girls restroom Low Right	WF-05082019-004278	2/12/2020	FT-FY20-012020-004278-A	<1	FT-FY20-012020-004278-B	<1
WS- 004279	5/6/2019	5/6/2020	Ground Floor	Food Prep Sink	In kitchen	WF-05062019-004279	2/12/2020	FT-FY20-012020-004279-A	<1	FT-FY20-012020-004279-B	<1
WS- 004280	5/6/2019	5/6/2020	Ground Floor	Break Room	In break room	WF-05062019-004280	2/12/2020	FT-FY20-012020-004280-A	<1	FT-FY20-012020-004280-B	<1