



# PALISADES COMM CEN LEAD WATER TEST RESULTS May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 PALISADES COMMUNITY CENTER	5/27/2016	WS-003818	Fountain	Ground Floor	Exterior adjacent to basketball court	Low WT-042916-3835- A	< 1	WT-042916-3835- B	< 1				
2 PALISADES COMMUNITY CENTER	5/27/2016	WS-003819	Fountain	Ground Floor	Exterior adjacent to basketball court	High WT-042916-3836- A	< 1	WT-042916-3836- B	< 1				
3 PALISADES COMMUNITY CENTER	5/27/2016	WS-003820	Fountain	Ground Floor	Exterior adjacent to Baseball field	Low WT-042916-3837- A	< 1	WT-042916-3837- B	< 1				
4 PALISADES COMMUNITY CENTER	5/27/2016	WS-003821	Fountain	Ground Floor	Exterior adjacent to baseball field	High WT-042916-3838- A	< 1	WT-042916-3838- B	< 1				
5 PALISADES COMMUNITY CENTER	5/27/2016	WS-003822	Fountain	Ground Floor	Exterior in playground	Low WT-042916-3839- A	< 1	WT-042916-3839- B	< 1				
6 PALISADES COMMUNITY CENTER	5/27/2016	WS-003823	Fountain	Ground Floor	Exterior in playground	High WT-042916-3840- A	< 1	WT-042916-3840- B	< 1				
7 PALISADES COMMUNITY CENTER	5/27/2016	WS-003824	Cooler	1	In exterior adjacent to office main suite	WT-042916-3841- A	< 1	WT-042916-3841- B	< 1				
8 PALISADES COMMUNITY CENTER	5/27/2016	WS-003825	Kitchen	1	In kitchen in rear of auditorium	WT-042916-3842- A	3.5	WT-042916-3842- B	< 1				
9 PALISADES COMMUNITY CENTER	5/27/2016	WS-003826	Utility	Basement	In basement closet adjacent to boiler room (water source)	WT-042916-3843- A	1.3	WT-042916-3843- B	< 1				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.