



# Parkview Recreation Center Lead in Water Test Results

## FY24 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011988	3/28/2024	3/28/2025	Ground Floor	Cooler	In multipurpose room adjacent to women's restroom	WF-03282024-011988	4/19/2024	FT-FY24-04022024-011988-A	<1	FT-FY24-04022024-011988-B	<1
WS- 011990	12/19/2023	12/19/2024	Ground Floor	Food Prep Sink	In kitchen	WF-12192023-011990	4/19/2024	FT-FY24-04022024-011990-A	<1	FT-FY24-04022024-011990-B	<1
WS- 011991	3/28/2024	3/28/2025	Ground Floor	Cooler	In multipurpose room adjacent to front desk	WF-03282024-011991	4/19/2024	FT-FY24-04022024-011991-A	<1	FT-FY24-04022024-011991-B	<1