



# Parkview RC Lead Water Test Results



## FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011988	5/14/2018	5/14/2019	Ground Floor	Cooler	In multipurpose room adjacent to women's restroom	WF-05142018-011988	2/4/2019	FT-FY19-012019-011988-A	<1	FT-FY19-012019-011988-B	<1
WS- 011991	5/14/2018	5/14/2019	Ground Floor	Cooler	In multipurpose room adjacent to front desk	WF-05142018-011991	2/4/2019	FT-FY19-012019-011991-A	<1	FT-FY19-012019-011991-B	<1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011990	5/14/2018	5/14/2019	Ground Floor	Food Prep Sink	In kitchen	WF-05142018-011990	2/4/2019	FT-FY19-012019-011990-A	<1	FT-FY19-012019-011990-B	<1