



# Parkview RC Lead in Water Test Results



## FY20 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011988	4/23/2019	4/23/2020	Ground Floor	Cooler	In multipurpose room adjacent to women's restroom	WF-04232019-011988	1/27/2020	FT-FY20-012020-011988-A	<1	FT-FY20-012020-011988-B	<1
WS- 011990	4/23/2019	4/23/2020	Ground Floor	Food Prep Sink	In kitchen	WF-04232019-011990	1/27/2020	FT-FY20-012020-011990-A	<1	FT-FY20-012020-011990-B	<1
WS- 011991	4/23/2019	4/23/2020	Ground Floor	Cooler	In multipurpose room adjacent to front desk	WF-04232019-011991	1/27/2020	FT-FY20-012020-011991-A	<1	FT-FY20-012020-011991-B	<1