



Petworth RC Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005393	5/15/2018	5/15/2019	1	Cooler	In main hall	WF-05152018-005393	2/14/2019	FT-FY19-022019-005393-A	<1	FT-FY19-022019-005393-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005392	5/15/2018	5/15/2019	1	Food Prep Sink	In kitchen	WF-05152018-005392	2/14/2019	FT-FY19-022019-005392-A	<1	FT-FY19-022019-005392-B	<1