



# Petworth Recreation Center Lead in Water Test Results

## FY23 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005392	2/17/2022	2/17/2023	1	Food Prep Sink	In kitchen	WF-02172022-005392	2/10/2023	FT-FY23-01192023-005392-A	<1	FT-FY23-01192023-005392-B	<1
WS- 005393	3/29/2022	3/29/2023	1	Cooler	In main hall	WF-03292022-005393	2/10/2023	FT-FY23-01192023-005393-A	<1	FT-FY23-01192023-005393-B	<1