



# Petworth Recreation Center Lead in Water Test Results

## FY24 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005392	12/11/2023	12/11/2024	1	Food Prep Sink	In kitchen	WF-12112023-005392	5/10/2024	FT-FY24-04242024-005392-A	<1	FT-FY24-04242024-005392-B	<1
WS- 005393	4/23/2024	4/23/2025	1	Cooler	In main hall	WF-04232024-005393	5/10/2024	FT-FY24-04242024-005393-A	<1	FT-FY24-04242024-005393-B	<1