



Phelps A.C.E. HS Lead in Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010683	6/5/2019	6/5/2020	Basement	Cooler	In hallway adjacent to room S005	WF-06052019-010683	1/13/2020	FT-FY20-122019-010683-A	<1	FT-FY20-122019-010683-B	<1
WS- 010684	6/5/2019	6/5/2020	Basement	Cooler	In hallway across from gym S001	WF-06052019-010684	1/13/2020	FT-FY20-122019-010684-A	<1	FT-FY20-122019-010684-B	<1
WS- 010686	6/5/2019	6/5/2020	1	Break Room	In break room A103	WF-06052019-010686	1/13/2020	FT-FY20-122019-010686-A	<1	FT-FY20-122019-010686-B	<1
WS- 010688	6/5/2019	6/5/2020	1	Break Room	In break room C105	WF-06052019-010688	1/13/2020	FT-FY20-122019-010688-A	<1	FT-FY20-122019-010688-B	<1
WS- 010689	6/5/2019	6/5/2020	1	Cooler	In hallway adjacent to room C108	WF-06052019-010689	1/13/2020	FT-FY20-122019-010689-A	<1	FT-FY20-122019-010689-B	<1
WS- 010690	6/5/2019	6/5/2020	1	Break Room	In break room 106M	WF-06052019-010690	1/13/2020	FT-FY20-122019-010690-A	<1	FT-FY20-122019-010690-B	<1
WS- 010698	6/5/2019	6/5/2020	1	Cooler	In hallway adjacent to room T104	WF-06052019-010698	1/13/2020	FT-FY20-122019-010698-A	<1	FT-FY20-122019-010698-B	<1
WS- 010700	6/5/2019	6/5/2020	1	Cooler	In hallway adjacent to room T106	WF-06052019-010700	1/13/2020	FT-FY20-122019-010700-A	<1	FT-FY20-122019-010700-B	<1
WS- 010703	6/5/2019	6/5/2020	1	Break Room	In break room 102A in library	WF-06052019-010703	1/13/2020	FT-FY20-122019-010703-A	<1	FT-FY20-122019-010703-B	<1
WS- 010704	6/5/2019	6/5/2020	1	Health Suite	In health suite 106E	WF-06052019-010704	1/13/2020	FT-FY20-122019-010704-A	<1	FT-FY20-122019-010704-B	<1
WS- 010707	6/5/2019	6/5/2020	2	Cooler	In hallway adjacent to room C211	WF-06052019-010707	1/13/2020	FT-FY20-122019-010707-A	<1	FT-FY20-122019-010707-B	<1
WS- 011468	6/5/2019	6/5/2020	2	Cooler	In hallway adjacent to room S206	WF-06052019-011468	1/13/2020	FT-FY20-122019-011468-A	<1	FT-FY20-122019-011468-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010691	7/9/2019	7/9/2020	1	Food Prep Sink	In kitchen first clockwise from entry door	WF-07092019-010691	1/13/2020	FT-FY20-122019-010691-A	<1	FT-FY20-122019-010691-B	<1
WS- 010693	7/9/2019	7/9/2020	1	Food Prep Sink	In kitchen third clockwise from entry door	WF-07092019-010693	1/13/2020	FT-FY20-122019-010693-A	<1	FT-FY20-122019-010693-B	<1