



Phelps A.C.E. HS Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010683	6/12/2018	6/12/2019	Basement	Cooler	In hallway adjacent to room S005	WF-06122018-010683	1/11/2019	FT-FY19-012019-010683-A	<1	FT-FY19-012019-010683-B	<1
WS- 010684	6/12/2018	6/12/2019	Basement	Cooler	In hallway across from gym S001	WF-06122018-010684	1/11/2019	FT-FY19-012019-010684-A	<1	FT-FY19-012019-010684-B	<1
WS- 010686	6/12/2018	6/12/2019	1	Break Room	In break room A103	WF-06122018-010686	1/11/2019	FT-FY19-012019-010686-A	<1	FT-FY19-012019-010686-B	<1
WS- 010687	6/12/2018	6/12/2019	1	Cooler	In hallway adjacent to room C110	WF-06122018-010687	1/11/2019	FT-FY19-012019-010687-A	<1	FT-FY19-012019-010687-B	<1
WS- 010688	6/12/2018	6/12/2019	1	Break Room	In break room C105	WF-06122018-010688	1/11/2019	FT-FY19-012019-010688-A	<1	FT-FY19-012019-010688-B	<1
WS- 010689	6/12/2018	6/12/2019	1	Cooler	In hallway adjacent to room C108	WF-06122018-010689	1/11/2019	FT-FY19-012019-010689-A	<1	FT-FY19-012019-010689-B	<1
WS- 010690	6/12/2018	6/12/2019	1	Break Room	In break room 106M	WF-06122018-010690	1/11/2019	FT-FY19-012019-010690-A	<1	FT-FY19-012019-010690-B	<1
WS- 010694	6/12/2018	6/12/2019	1	Ice Maker	In kitchen (ice maker)	WF-06122018-010694	1/11/2019	FT-FY19-012019-010694-A	<1	FT-FY19-012019-010694-B	<1
WS- 010698	6/12/2018	6/12/2019	1	Cooler	In hallway adjacent to room T104	WF-06122018-010698	1/11/2019	FT-FY19-012019-010698-A	<1	FT-FY19-012019-010698-B	<1
WS- 010700	6/12/2018	6/12/2019	1	Cooler	In hallway adjacent to room T106	WF-06122018-010700	1/11/2019	FT-FY19-012019-010700-A	<1	FT-FY19-012019-010700-B	<1
WS- 010703	6/12/2018	6/12/2019	1	Break Room	In break room 102A in library	WF-06122018-010703	1/11/2019	FT-FY19-012019-010703-A	<1	FT-FY19-012019-010703-B	<1
WS- 010704	6/12/2018	6/12/2019	1	Health Suite	In health suite 106E	WF-06122018-010704	1/11/2019	FT-FY19-012019-010704-A	<1	FT-FY19-012019-010704-B	<1
WS- 010707	6/12/2018	6/12/2019	2	Cooler	In hallway adjacent to room C211	WF-06122018-010707	1/11/2019	FT-FY19-012019-010707-A	<1	FT-FY19-012019-010707-B	<1
WS- 011484	12/20/2018	12/20/2019	1	Cooler	In Spingarn field locker room (right)	WF-12202018-011484	1/11/2019	FT-FY19-012019-011484-A	<1	FT-FY19-012019-011484-B	<1
WS- 011485	12/20/2018	12/20/2019	1	Cooler	In Spingarn field locker room (left)	WF-12202018-011485	1/11/2019	FT-FY19-012019-011485-A	<1	FT-FY19-012019-011485-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)			
WS- 010691	1	Food Prep Sink	In kitchen first clockwise from entry door	1/11/2019	FT-FY19-012019-010691-A	<1	FT-FY19-012019-010691-B	<1			
WS- 010693	1	Food Prep Sink	In kitchen third clockwise from entry door	1/11/2019	FT-FY19-012019-010693-A	<1	FT-FY19-012019-010693-B	<1			