



PLUMMER LEAD WATER TEST RESULTS

May 12th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest Results
1	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002649	Utility	2	In custodian closet next to cafeteria(next to the main supply)	WT-042916-2666- A	< 1	WT-042916-2666- B	< 1			
2	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002650	Break Room	1	In staff lounge 122	WT-042916-2667- A	< 1	WT-042916-2667- B	< 1			
3	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002651	Cooler	1	In hallway adjacent to room 122 Low	WT-042916-2668- A	< 1	WT-042916-2668- B	< 1			
4	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002652	Cooler	1	In hallway adjacent to room 122 Right High	WT-042916-2669- A	< 1	WT-042916-2669- B	< 1			
5	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002653	Health Suite	1	In health suite	WT-042916-2670- A	< 1	WT-042916-2670- B	< 1			
6	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002654	Cooler	1	In auditorium Left Low	WT-042916-2671- A	< 1	WT-042916-2671- B	< 1			
7	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002655	Cooler	1	In auditorium Right High	WT-042916-2672- A	< 1	WT-042916-2672- B	< 1			
8	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002656	Fountain	2	In classroom 201 Right	WT-042916-2673- A	< 1	WT-042916-2673- B	< 1			
9	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002657	Classroom	2	In classroom 201 Left	WT-042916-2674- A	< 1	WT-042916-2674- B	< 1			
10	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002658	Fountain	2	In classroom 202 Right	WT-042916-2675- A	< 1	WT-042916-2675- B	< 1			
11	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002659	Classroom	2	In classroom 202 Left	WT-042916-2676- A	< 1	WT-042916-2676- B	< 1			
12	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002660	Fountain	2	In classroom 203 Right	WT-042916-2677- A	< 1	WT-042916-2677- B	< 1			
13	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002661	Classroom	2	In classroom 203 Left	WT-042916-2678- A	< 1	WT-042916-2678- B	< 1			
14	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002662	Fountain	2	In classroom 204 Right	WT-042916-2679- A	< 1	WT-042916-2679- B	< 1			
15	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002663	Classroom	2	In classroom 204 Left	WT-042916-2680- A	< 1	WT-042916-2680- B	< 1			
16	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002664	Fountain	2	In classroom 206 Right	WT-042916-2681- A	< 1	WT-042916-2681- B	< 1			
17	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002665	Classroom	2	In classroom 206 Left	WT-042916-2682- A	< 1	WT-042916-2682- B	< 1			
18	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002666	Fountain	2	In classroom 212 Right High	WT-042916-2683- A	< 1	WT-042916-2683- B	< 1			
19	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002667	Classroom	2	In classroom 212 Left	WT-042916-2684- A	< 1	WT-042916-2684- B	< 1			
20	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002668	Cooler	2	In hallway adjacent to room 217 Left Low	WT-042916-2685- A	< 1	WT-042916-2685- B	< 1			
21	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002669	Cooler	2	In hallway adjacent to room 217 Right High	WT-042916-2686- A	< 1	WT-042916-2686- B	< 1			
22	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002670	Fountain	2	In classroom 214 Right	WT-042916-2687- A	< 1	WT-042916-2687- B	< 1			
23	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002671	Classroom	2	In classroom 214 Left	WT-042916-2688- A	< 1	WT-042916-2688- B	< 1			
24	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002672	Fountain	2	In classroom 219 Right	WT-042916-2689- A	< 1	WT-042916-2689- B	< 1			
25	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002673	Classroom	2	In classroom 219	WT-042916-2690- A	< 1	WT-042916-2690- B	< 1			
26	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002674	Fountain	2	In classroom 216 Right	WT-042916-2691- A	< 1	WT-042916-2691- B	< 1			
27	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002675	Classroom	2	In classroom 216 Mid	WT-042916-2692- A	< 1	WT-042916-2692- B	< 1			
28	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002676	Fountain	2	In classroom 221 Right	WT-042916-2693- A	< 1	WT-042916-2693- B	< 1			



PLUMMER LEAD WATER TEST RESULTS

May 12th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest Results
29	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002677	Classroom	2	In classroom 221 Left	WT-042916-2694- A	< 1	WT-042916-2694- B	< 1			
30	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002678	Fountain	2	In cafeteria	WT-042916-2695- A	< 1	WT-042916-2695- B	< 1			
31	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002679	Kitchen	2	In kitchen	WT-042916-2696- A	< 1	WT-042916-2696- B	< 1			
32	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002680	Cooler	3	In hallway adjacent to room 309 Left Low	WT-042916-2697- A	< 1	WT-042916-2697- B	< 1			
33	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002681	Fountain	3	In hallway adjacent to room 309 Right High	WT-042916-2698- A	< 1	WT-042916-2698- B	< 1			
34	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002682	Classroom	3	In classroom 301 Left	WT-042916-2699- A	< 1	WT-042916-2699- B	< 1			
35	PLUMMER ELEMENTARY SCHOOL	5/4/2016	WS- 002683	Classroom	3	In classroom 301 Right	WT-042916-2700- A	< 1	WT-042916-2700- B	< 1			

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.