



Randall RC Lead in Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 006241	5/2/2019	5/2/2020	Ground Floor	Food Prep Sink	In kitchen	WF-05022019-006241	3/3/2020	FT-FY20-012020-006241-A	<1	FT-FY20-012020-006241-B	<1
WS- 006242	5/2/2019	5/2/2020	Ground Floor	Cooler	In hallway across from girls' restroom	WF-05022019-006242	3/3/2020	FT-FY20-012020-006242-A	<1	FT-FY20-012020-006242-B	<1