



Raymond RC Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011584	4/17/2018	4/17/2019	1	Cooler	In hallway adjacent to room 110	High Left	WF-04172018-011584	2/19/2019	FT-FY19-022019-011584-A	<1	FT-FY19-022019-011584-B	<1
WS- 011585	4/17/2018	4/17/2019	1	Cooler	In hallway adjacent to room 110	Low Right	WF-04172018-011585	2/19/2019	FT-FY19-022019-011585-A	<1	FT-FY19-022019-011585-B	<1
WS- 011590	4/17/2018	4/17/2019	2	Cooler	In hallway adjacent to mens' restroom	High Left	WF-04172018-011590	2/19/2019	FT-FY19-022019-011590-A	<1	FT-FY19-022019-011590-B	<1
WS- 011591	4/17/2018	4/17/2019	2	Cooler	In hallway adjacent to mens' restroom	Low Right	WF-04172018-011591	2/19/2019	FT-FY19-022019-011591-A	<1	FT-FY19-022019-011591-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011586	4/17/2018	4/17/2019	2	Food Prep Sink	In kitchen 209		WF-04172018-011586	2/19/2019	FT-FY19-022019-011586-A	<1	FT-FY19-022019-011586-B	<1