

Roosevelt High Renovation Project



Monitoring Well Installation in Preparation of Geothermal



Clerestory Steel Installation at Area A



13th Street Main Entrance Reconstruction



Before - Completion of Pepco Service duct bank



Completion of Pepco Service duct bank



11/08/2014 Activities



Setting HVAC unit to Serve the Pool



Setting HVAC unit to Serve the Pool



New Cooling Tower Set in Place



Rainwater Cisterns for the Waterworks Courtyard



Rainwater Cisterns for the Waterworks Courtyard




Rainwater Cisterns for the Waterworks Courtyard



Placement of the Rainwater Cisterns into Place



Placement of the Rainwater Cisterns into Place



AHU #4 Serving the Atrium being set into place



AHU #4 Serving the Atrium being set into place



AHU #4 Serving the Atrium being set into place



Before - Area A 1st Floor



Area A 1st Floor



Before - Area A Roof



Area A Roof Steel



Area A Roof



Area A Roof Unit



Before - Waterworks Courtyard East Elevation



Waterworks Rainwater Tanks set and Pad for Above Ground Poured



Before - Waterworks West Elevation



Waterworks Rainwater Tanks set and Pad for Above Ground Poured



Area B Stud Framing and HM Door Installation



Area B Fly loft Exterior Masonry Restoration



Before - Area C Mechanical




Area C Mechanical Insulation Beginning



Area C 1st Floor Wall Framing and MEP Rough-in



Area C/D 2nd Floor Rough-in is Ongoing



Area C/D 2nd floor Rough-in and Framing



Area C/D 3rd MEP Rough-ins



Area C/D 3rd Wall Steel Stud Framing



Before - Atrium



Atrium East Elevation and New Stair Framing



Arrival of New Exterior Windows



200 Ton Crane on West Elevation For Atrium Columns



Before - Pavilion Auger Cast Piles




Pavilion Grade Beam Reinforcement



Before - Area E Gymnasium



Area E Gymnasium



Before - Area E Stairs West of the Gymnasium



Area E East Side Demolition



Before - Area E 1st Floor Locker Rooms



Area E Locker Rooms CMU and MEP Rough-ins

