

Roosevelt High Renovation Project

01/15/2015



Staking grade elevations in the North side of the site prior to Geo-Thermal work



Staking grade elevations in the North side of the site prior to Geo-Thermal work



(Before) Clerestory Steel Installation at Area A



Clerestory Steel Installation at Area A complete, winterization shown on the interior



(Before) 13th Street Main Entrance Reconstruction



13th Street Main Entrance Cupola Erection



13th Street Main Entrance Cupola Erection



(Before) Area A Ground Floor Garage



Ground floor level of Area A – Ceiling Grid



(Before) Area A 1st Floor



Area A 1st Floor - Fireproofing



(Before) Area A 1st Floor other side of wall from previous slide



Area A 1st Floor - Drywall Installation has begun



Screen wall steel structure and curbs are install on areas A & B roof



(Before) Waterworks Rainwater Tanks set and Pad for Above Ground Poured



Waterworks - Winterization and concrete wall poured.



(Before) Waterworks Rainwater Tanks set and Pad for Above Ground Poured



Waterworks West Elevation – Winterization and new windows.



Ground Floor Area C – Part of the Switch Gear is being installed




(Before) Ground Floor Areas C/D - Mechanical Insulation Beginning



Ground Floor Areas C/D - Mechanical insulations is near complete



Ground Floor Areas C/D – Media Center opening



Electrical Room Panel Boxes are being installed



1st Floor Historical Lobby



1st Floor Areas C/D – Above ceiling work is still ongoing




1st Floor Drywall Mock-up Revision



1st Floor Drywall Mock-up Original



(Before) Area C/D 2nd Floor Rough-in is Ongoing



Areas C/D 2nd Floor CMU is complete



(Before) Atrium East Elevation and New Stair Framing



Main Stair leading into the Atrium



Atrium Steel Columns



Atrium – Installation of Tube steel for skylight support



Slate and gutter work in the Atrium



Slate and gutter work in the Atrium



(Before) Pavilion Grade Beam Reinforcement



Pavilion concrete walls and steel erection



Pavilion concrete walls and steel erection



Pavilion concrete walls and steel erection



(Before) Area E East Side Demolition




Area E Gymnasium – Bleacher Steel



(Before) Area E Gymnasium



Area E Gymnasium



(Before) Area E New Elevator Layout



Area E – Masonry work



Area E Pool – Storefront openings created and scaffolding installation is ongoing



Area E Pool – Storefront openings created and scaffolding installation is ongoing

