



# ROSE PARK REC LEAD WATER TEST RESULTS

May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	ROSE PARK RECREATION CENTER	5/28/2016	WS-006421	Fountain	Ground Floor	Exterior adjacent to tennis court Low	WT-042916-6438- A	< 1	WT-042916-6438- B	< 1				
2	ROSE PARK RECREATION CENTER	5/28/2016	WS-006422	Fountain	Ground Floor	Exterior adjacent to tennis court High	WT-042916-6439- A	< 1	WT-042916-6439- B	< 1				
3	ROSE PARK RECREATION CENTER	5/28/2016	WS-006423	Cooler	Ground Floor	In hall adjacent to girls restroom (water source)	WT-042916-6440- A	< 1	WT-042916-6440- B	< 1				
4	ROSE PARK RECREATION CENTER	5/27/2016	WS-006424	Fountain	Ground Floor	Exterior in play area associated with camp berry ages 2-6 Mid	WT-042916-6441- A	< 1	WT-042916-6441- B	< 1				
5	ROSE PARK RECREATION CENTER	5/28/2016	WS-006425	Fountain	Ground Floor	Exterior in play area associated with camp berry ages 2-6 Left	WT-042916-6442- A	< 1	WT-042916-6442- B	< 1				
6	ROSE PARK RECREATION CENTER	5/28/2016	WS-006426	Fountain	Ground Floor	Exterior in play area associated with camp berry ages 2-6 ( Dogs fountain) Right	WT-042916-6443- A	< 1	WT-042916-6443- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.