



# ROSE PARK REC LEAD WATER TEST RESULTS



Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)
1 ROSE PARK RECREATION CENTER	WS- 006423	9/22/2016	Ground Floor	Cooler	In hallway adjacent to girls' restroom (water source)	FT-82016-006423-A	< 1	FT-82016-006423-B	< 1