



Rose Park RC Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 006423	5/18/2018	5/18/2019	Ground Floor	Cooler	In hallway adjacent to girls' restroom (water source)	WF-05182018-006423	1/25/2019	FT-FY19-012019-006423-A	<1	FT-FY19-012019-006423-B	<1