



Rosedale RC Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011530	4/12/2018	4/12/2019	1	Cooler	In hallway adjacent to office 102	High Left	WF-04122018-011530	3/6/2019	FT-FY19-022019-011530-A	<1	FT-FY19-022019-011530-B	<1
WS- 011531	4/12/2018	4/12/2019	1	Cooler	In hallway adjacent to office 102	Low Right	WF-04122018-011531	3/6/2019	FT-FY19-022019-011531-A	<1	FT-FY19-022019-011531-B	<1
WS- 011541	4/12/2018	4/12/2019	1	Cooler	In library		WF-04122018-011541	3/6/2019	FT-FY19-022019-011541-A	<1	FT-FY19-022019-011541-B	<1
WS- 011542	4/12/2018	4/12/2019	1	Break Room	In work room in library	Left	WF-04122018-011542	3/6/2019	FT-FY19-022019-011542-A	<1	FT-FY19-022019-011542-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011528	4/12/2018	4/12/2019	1	Food Prep Sink	In kitchen 119	Left	WF-04122018-011528	3/6/2019	FT-FY19-022019-011528-A	<1	FT-FY19-022019-011528-B	<1
WS- 011534	5/15/2018	5/15/2019	1	Food Prep Sink	In kitchen 106	Left	WF-05152018-011534	3/6/2019	FT-FY19-022019-011534-A	<1	FT-FY19-022019-011534-B	<1
WS- 011536	4/12/2018	4/12/2019	1	Food Prep Sink	In kitchen 106	Right	WF-04122018-011536	3/6/2019	FT-FY19-022019-011536-A	<1	FT-FY19-022019-011536-B	<1