



Rosedale RC Lead in Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation													
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-011528	3/26/2019	3/26/2020	1	Food Prep Sink	In kitchen 119	Left	WF-03262019-011528	3/3/2020	FT-FY20-012020-011528-A	<1	FT-FY20-012020-011528-B	<1	
WS-011530	9/18/2019	9/18/2020	1	Cooler	In hallway adjacent to office 102	High Left	WF-09182019-011530	3/3/2020	FT-FY20-012020-011530-A	<1	FT-FY20-012020-011530-B	<1	
WS-011531	9/18/2019	9/18/2020	1	Cooler	In hallway adjacent to office 102	Low Right	WF-09182019-011531	3/3/2020	FT-FY20-012020-011531-A	<1	FT-FY20-012020-011531-B	<1	
WS-011534	3/26/2019	3/26/2020	1	Food Prep Sink	In kitchen 106	Left	WF-03262019-011534	3/3/2020	FT-FY20-012020-011534-A	<1	FT-FY20-012020-011534-B	<1	
WS-011536	3/26/2019	3/26/2020	1	Food Prep Sink	In kitchen 106	Right	WF-03262019-011536	3/3/2020	FT-FY20-012020-011536-A	<1	FT-FY20-012020-011536-B	<1	
WS-011541	5/9/2019	5/9/2020	1	Cooler	In library		WF-05092019-011541	3/3/2020	FT-FY20-012020-011541-A	<1	FT-FY20-012020-011541-B	<1	
WS-011542	3/26/2019	3/26/2020	1	Break Room	In work room in library	Left	WF-03262019-011542	3/3/2020	FT-FY20-012020-011542-A	<1	FT-FY20-012020-011542-B	<1	