



Rosedale Recreation Center Lead in Water Test Results

FY23 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 011528	1/4/2023	1/4/2024	1	Food Prep Sink	In kitchen 119	Left	WF-01042023-011528	3/2/2023	FT-FY23-02022023-011528-A	<1	FT-FY23-02022023-011528-B	<1
WS- 011530	3/14/2022	3/14/2023	1	Cooler	In hallway adjacent to office 102	High Left	WF-03142022-011530	3/2/2023	FT-FY23-02022023-011530-A	<1	FT-FY23-02022023-011530-B	<1
WS- 011531	3/14/2022	3/14/2023	1	Cooler	In hallway adjacent to office 102	Low Right	WF-03142022-011531	3/2/2023	FT-FY23-02022023-011531-A	<1	FT-FY23-02022023-011531-B	<1
WS- 011534	1/4/2023	1/4/2024	1	Food Prep Sink	In kitchen 106	Left	WF-01042023-011534	3/2/2023	FT-FY23-02022023-011534-A	<1	FT-FY23-02022023-011534-B	<1
WS- 011536	1/4/2023	1/4/2024	1	Food Prep Sink	In kitchen 106	Right	WF-01042023-011536	3/2/2023	FT-FY23-02022023-011536-A	<1	FT-FY23-02022023-011536-B	<1
WS- 011541	3/14/2022	3/14/2023	1	Cooler	In library		WF-03142022-011541	3/2/2023	FT-FY23-02022023-011541-A	<1	FT-FY23-02022023-011541-B	<1
WS- 011542	3/14/2022	3/14/2023	1	Break Room	In work room in library	Left	WF-03142022-011542	3/2/2023	FT-FY23-02022023-011542-A	<1	FT-FY23-02022023-011542-B	<1