



# Rosedale Recreation Center Lead in Water Test Results

## FY24 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 011528	11/27/2023	11/27/2024	1	Food Prep Sink	In kitchen 119	Left	WF-11272023-011528	3/18/2024	FT-FY24-03052024-011528-A	<1	FT-FY24-03052024-011528-B	<1
WS- 011530	2/28/2024	2/28/2025	1	Cooler	In hallway adjacent to office 102	High Left	WF-02282024-011530	3/18/2024	FT-FY24-03052024-011530-A	<1	FT-FY24-03052024-011530-B	<1
WS- 011531	2/28/2024	2/28/2025	1	Cooler	In hallway adjacent to office 102	Low Right	WF-02282024-011531	3/18/2024	FT-FY24-03052024-011531-A	<1	FT-FY24-03052024-011531-B	<1
WS- 011534	11/27/2023	11/27/2024	1	Food Prep Sink	In kitchen 106	Left	WF-11272023-011534	3/18/2024	FT-FY24-03052024-011534-A	<1	FT-FY24-03052024-011534-B	<1
WS- 011536	11/27/2023	11/27/2024	1	Food Prep Sink	In kitchen 106	Right	WF-11272023-011536	3/18/2024	FT-FY24-03052024-011536-A	<1	FT-FY24-03052024-011536-B	<1
WS- 011541	2/28/2024	2/28/2025	1	Cooler	In library		WF-02282024-011541	3/18/2024	FT-FY24-03052024-011541-A	<1	FT-FY24-03052024-011541-B	<1
WS- 011542	2/28/2024	2/28/2025	1	Break Room	In work room in library	Left	WF-02282024-011542	3/18/2024	FT-FY24-03052024-011542-A	<1	FT-FY24-03052024-011542-B	<1