



Ross Elementary School Lead in Water Test Results

FY22 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 007909	8/18/2021	8/18/2022	Ground Floor	Fountain	Outdoor water fountain by playground	WF-08182021-007909	11/22/2021	FT-FY22-11122021-007909-A	<1	FT-FY22-11122021-007909-B	<1
WS- 007910	8/18/2021	8/18/2022	Basement	Bottle Filler	In staff lounge B06	WF-08182021-007910	11/22/2021	FT-FY22-11122021-007910-A	<1	FT-FY22-11122021-007910-B	<1
WS- 007911	8/18/2021	8/18/2022	Basement	Cooler	In staff lounge B06	WF-08182021-007911	11/22/2021	FT-FY22-11122021-007911-A	<1	FT-FY22-11122021-007911-B	1.2
WS- 007912	8/18/2021	8/18/2022	Basement	Break Room	In staff lounge B06	WF-08182021-007912	11/22/2021	FT-FY22-11122021-007912-A	<1	FT-FY22-11122021-007912-B	<1
WS- 007913	8/18/2021	8/18/2022	Basement	Break Room	In lactation room 007	WF-08182021-007913	11/22/2021	FT-FY22-11122021-007913-A	<1	FT-FY22-11122021-007913-B	<1
WS- 007914	8/18/2021	8/18/2022	Basement	Combo Fountain	In lactation room 007	WF-08182021-007914	11/22/2021	FT-FY22-11122021-007914-A	<1	FT-FY22-11122021-007914-B	<1
WS- 007917	8/18/2021	8/18/2022	3	Combo Fountain	In art lab 302	WF-08182021-007917	11/22/2021	FT-FY22-11122021-007917-A	<1	FT-FY22-11122021-007917-B	<1
WS- 007920	8/18/2021	8/18/2022	3	Combo Fountain	In music room 303	WF-08182021-007920	11/22/2021	FT-FY22-11122021-007920-A	<1	FT-FY22-11122021-007920-B	<1
WS- 010096	5/25/2021	5/25/2022	Basement	Bottle Filler	In cafeteria	WF-05252021-010096	11/22/2021	FT-FY22-11122021-010096-A	<1	FT-FY22-11122021-010096-B	<1
WS- 010097	5/25/2021	5/25/2022	2	Bottle Filler	In hallway adjacent to room 204	WF-05252021-010097	11/22/2021	FT-FY22-11122021-010097-A	<1	FT-FY22-11122021-010097-B	<1
WS- 010098	5/25/2021	5/25/2022	1	Bottle Filler	In hallway adjacent to room 105	WF-05252021-010098	11/22/2021	FT-FY22-11122021-010098-A	<1	FT-FY22-11122021-010098-B	<1
WS- 010099	5/25/2021	5/25/2022	Basement	Bottle Filler	In hallway adjacent to main office	WF-05252021-010099	11/22/2021	FT-FY22-11122021-010099-A	<1	FT-FY22-11122021-010099-B	<1
WS- 010327	9/1/2021	9/1/2022	1	Classroom Faucet	In classroom 105	WF-09012021-010327	11/22/2021	FT-FY22-11122021-010327-A	<1	FT-FY22-11122021-010327-B	<1
WS- 010328	9/1/2021	9/1/2022	1	Classroom Faucet	In classroom 106	WF-09012021-010328	11/22/2021	FT-FY22-11122021-010328-A	<1	FT-FY22-11122021-010328-B	<1
WS- 010329	9/1/2021	9/1/2022	1	Classroom Faucet	In classroom 109	WF-09012021-010329	11/22/2021	FT-FY22-11122021-010329-A	<1	FT-FY22-11122021-010329-B	<1
WS- 010330	9/1/2021	9/1/2022	1	Classroom Faucet	In classroom 102	WF-09012021-010330	11/22/2021	FT-FY22-11122021-010330-A	<1	FT-FY22-11122021-010330-B	<1
WS- 010334	5/25/2021	5/25/2022	Basement	Health Suite	In health suite	WF-05252021-010334	11/22/2021	FT-FY22-11122021-010334-A	<1	FT-FY22-11122021-010334-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010338	1/14/2021	1/14/2022	Basement	Food Prep Sink	In kitchen	WF-01142021-010338	11/22/2021	FT-FY22-11122021-010338-A	<1	FT-FY22-11122021-010338-B	<1