



Ross ES Lead Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010097	5/6/2019	5/6/2020	2	Bottle Filler	In hallway adjacent to room 204	WF-05062019-010097	11/7/2019	FT-FY20-102019-010097-A	<1	FT-FY20-102019-010097-B	1.7
WS- 010098	5/6/2019	5/6/2020	1	Bottle Filler	In hallway adjacent to room 105	WF-05062019-010098	11/7/2019	FT-FY20-102019-010098-A	<1	FT-FY20-102019-010098-B	<1
WS- 010099	5/6/2019	5/6/2020	Basement	Bottle Filler	In hallway adjacent to main office	WF-05062019-010099	11/7/2019	FT-FY20-102019-010099-A	<1	FT-FY20-102019-010099-B	<1
WS- 010319	5/6/2019	5/6/2020	2	Cooler	In hallway adjacent to room 204 High Left	WF-05062019-010319	11/7/2019	FT-FY20-102019-010319-A	<1	FT-FY20-102019-010319-B	<1
WS- 010320	5/6/2019	5/6/2020	2	Cooler	In hallway adjacent to room 204 Low Right	WF-05062019-010320	11/7/2019	FT-FY20-102019-010320-A	<1	FT-FY20-102019-010320-B	<1
WS- 010325	5/6/2019	5/6/2020	1	Cooler	In hallway adjacent to room 105 High Left	WF-05062019-010325	11/7/2019	FT-FY20-102019-010325-A	<1	FT-FY20-102019-010325-B	<1
WS- 010326	5/6/2019	5/6/2020	1	Cooler	In hallway adjacent to room 105 Low Right	WF-05062019-010326	11/7/2019	FT-FY20-102019-010326-A	<1	FT-FY20-102019-010326-B	<1
WS- 010327	9/20/2019	9/20/2020	1	Classroom Faucet	In classroom 105	WF-09202019-010327	11/7/2019	FT-FY20-102019-010327-A	<1	FT-FY20-102019-010327-B	<1
WS- 010328	9/20/2019	9/20/2020	1	Classroom Faucet	In classroom 106	WF-09202019-010328	11/7/2019	FT-FY20-102019-010328-A	<1	FT-FY20-102019-010328-B	<1
WS- 010329	9/20/2019	9/20/2020	1	Classroom Faucet	In classroom 109	WF-09202019-010329	11/7/2019	FT-FY20-102019-010329-A	<1	FT-FY20-102019-010329-B	<1
WS- 010330	9/20/2019	9/20/2020	1	Classroom Faucet	In classroom 102	WF-09202019-010330	11/7/2019	FT-FY20-102019-010330-A	2.3	FT-FY20-102019-010330-B	<1
WS- 010331	5/6/2019	5/6/2020	Basement	Cooler	In hallway adjacent to main office Low Right	WF-05062019-010331	11/7/2019	FT-FY20-102019-010331-A	<1	FT-FY20-102019-010331-B	<1
WS- 010332	5/6/2019	5/6/2020	Basement	Cooler	In hallway adjacent to main office High Left	WF-05062019-010332	11/7/2019	FT-FY20-102019-010332-A	<1	FT-FY20-102019-010332-B	<1
WS- 010333	5/6/2019	5/6/2020	Basement	Break Room	In staff lounge B06	WF-05062019-010333	11/7/2019	FT-FY20-102019-010333-A	<1	FT-FY20-102019-010333-B	<1
WS- 010334	5/6/2019	5/6/2020	Basement	Health Suite	In health suite	WF-05062019-010334	11/7/2019	FT-FY20-102019-010334-A	<1	FT-FY20-102019-010334-B	<1
WS- 010335	5/6/2019	5/6/2020	Basement	Cooler	In cafeteria High Left	WF-05062019-010335	11/7/2019	FT-FY20-102019-010335-A	<1	FT-FY20-102019-010335-B	<1
WS- 010336	5/6/2019	5/6/2020	Basement	Cooler	In cafeteria Low Right	WF-05062019-010336	11/7/2019	FT-FY20-102019-010336-A	<1	FT-FY20-102019-010336-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010338	7/8/2019	7/8/2020	Basement	Food Prep Sink	In kitchen	WF-07082019-010338	11/7/2019	FT-FY20-102019-010338-A	<1	FT-FY20-102019-010338-B	<1