



Ross Elementary School Lead in Water Test Results

FY23 Filter Test

| Less than 5ppb - Devices requiring no remediation | | | | | | | | | | | | |
|---|-----------------------|------------------------|----------|------------------|------------------------------------|---------------------|--------------------|---------------------------|----------------------------------|---------------------------|----------------------------------|-----|
| Record ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) | |
| WS- 007910 | 5/17/2022 | 5/17/2023 | Basement | Bottle Filler | In staff lounge B06 | WF-05172022-007910 | 1/9/2023 | FT-FY23-11182022-007910-A | <1 | FT-FY23-11182022-007910-B | 1.5 | |
| WS- 007911 | 5/17/2022 | 5/17/2023 | Basement | Cooler | In staff lounge B06 | WF-05172022-007911 | 1/9/2023 | FT-FY23-11182022-007911-A | <1 | FT-FY23-11182022-007911-B | 2.7 | |
| WS- 007912 | 5/17/2022 | 5/17/2023 | Basement | Break Room | In staff lounge B06 | WF-05172022-007912 | 1/9/2023 | FT-FY23-11182022-007912-A | 2.6 | FT-FY23-11182022-007912-B | 1.2 | |
| WS- 007913 | 5/17/2022 | 5/17/2023 | Basement | Break Room | In lactation room 007 | WF-05172022-007913 | 1/9/2023 | FT-FY23-11182022-007913-A | <1 | FT-FY23-11182022-007913-B | <1 | |
| WS- 007917 | 5/17/2022 | 5/17/2023 | 3 | Combo Fountain | In art lab 302 | WF-05172022-007917 | 1/9/2023 | FT-FY23-11182022-007917-A | 4.6 | FT-FY23-11182022-007917-B | 1.3 | |
| WS- 007920 | 5/17/2022 | 5/17/2023 | 3 | Combo Fountain | In music room 303 | WF-05172022-007920 | 1/9/2023 | FT-FY23-11182022-007920-A | 2.5 | FT-FY23-11182022-007920-B | 1.0 | |
| WS- 010096 | 5/17/2022 | 5/17/2023 | Basement | Bottle Filler | In cafeteria | WF-05172022-010096 | 1/9/2023 | FT-FY23-11182022-010096-A | 2.3 | FT-FY23-11182022-010096-B | 2.0 | |
| WS- 010097 | 5/17/2022 | 5/17/2023 | 2 | Bottle Filler | In hallway adjacent to room 204 | WF-05172022-010097 | 1/9/2023 | FT-FY23-11182022-010097-A | 1.9 | FT-FY23-11182022-010097-B | 1.3 | |
| WS- 010098 | 5/17/2022 | 5/17/2023 | 1 | Bottle Filler | In hallway adjacent to room 105 | WF-05172022-010098 | 1/9/2023 | FT-FY23-11182022-010098-A | 4.0 | FT-FY23-11182022-010098-B | 1.7 | |
| WS- 010099 | 5/17/2022 | 5/17/2023 | Basement | Bottle Filler | In hallway adjacent to main office | WF-05172022-010099 | 1/9/2023 | FT-FY23-11182022-010099-A | 1.0 | FT-FY23-11182022-010099-B | 1.2 | |
| WS- 010319 | 5/17/2022 | 5/17/2023 | 2 | Cooler | In hallway adjacent to room 204 | High Left | WF-05172022-010319 | 1/9/2023 | FT-FY23-11182022-010319-A | 4.4 | FT-FY23-11182022-010319-B | <1 |
| WS- 010320 | 5/17/2022 | 5/17/2023 | 2 | Cooler | In hallway adjacent to room 204 | Low Right | WF-05172022-010320 | 1/9/2023 | FT-FY23-11182022-010320-A | 1.2 | FT-FY23-11182022-010320-B | 4.7 |
| WS- 010325 | 5/17/2022 | 5/17/2023 | 1 | Cooler | In hallway adjacent to room 105 | High Left | WF-05172022-010325 | 1/9/2023 | FT-FY23-11182022-010325-A | <1 | FT-FY23-11182022-010325-B | 1.1 |
| WS- 010326 | 5/17/2022 | 5/17/2023 | 1 | Cooler | In hallway adjacent to room 105 | Low Right | WF-05172022-010326 | 1/9/2023 | FT-FY23-11182022-010326-A | 3.1 | FT-FY23-11182022-010326-B | 2.8 |
| WS- 010327 | 8/23/2022 | 8/23/2023 | 1 | Classroom Faucet | In classroom 105 | WF-08232022-010327 | 1/9/2023 | FT-FY23-11182022-010327-A | 2.4 | FT-FY23-11182022-010327-B | <1 | |
| WS- 010328 | 8/23/2022 | 8/23/2023 | 1 | Classroom Faucet | In classroom 106 | WF-08232022-010328 | 1/9/2023 | FT-FY23-11182022-010328-A | 2.6 | FT-FY23-11182022-010328-B | 1.3 | |
| WS- 010329 | 8/23/2022 | 8/23/2023 | 1 | Classroom Faucet | In classroom 109 | WF-08232022-010329 | 1/9/2023 | FT-FY23-11182022-010329-A | 3.5 | FT-FY23-11182022-010329-B | 1.0 | |
| WS- 010330 | 8/23/2022 | 8/23/2023 | 1 | Classroom Faucet | In classroom 102 | WF-08232022-010330 | 1/9/2023 | FT-FY23-11182022-010330-A | 1.8 | FT-FY23-11182022-010330-B | 1.2 | |
| WS- 010331 | 5/17/2022 | 5/17/2023 | Basement | Cooler | In hallway adjacent to main office | Low Right | WF-05172022-010331 | 1/9/2023 | FT-FY23-11182022-010331-A | 1.2 | FT-FY23-11182022-010331-B | 4.1 |
| WS- 010332 | 5/17/2022 | 5/17/2023 | Basement | Cooler | In hallway adjacent to main office | High Left | WF-05172022-010332 | 1/9/2023 | FT-FY23-11182022-010332-A | <1 | FT-FY23-11182022-010332-B | 3.0 |
| WS- 010334 | 5/17/2022 | 5/17/2023 | Basement | Health Suite | In health suite | WF-05172022-010334 | 1/9/2023 | FT-FY23-11182022-010334-A | 1.7 | FT-FY23-11182022-010334-B | 2.1 | |
| WS- 010335 | 5/17/2022 | 5/17/2023 | Basement | Cooler | In cafeteria | High Left | WF-05172022-010335 | 1/9/2023 | FT-FY23-11182022-010335-A | 1.2 | FT-FY23-11182022-010335-B | 1.2 |
| WS- 010336 | 5/17/2022 | 5/17/2023 | Basement | Cooler | In cafeteria | Low Right | WF-05172022-010336 | 1/9/2023 | FT-FY23-11182022-010336-A | 1.4 | FT-FY23-11182022-010336-B | 3.7 |

Food Prep Sink

| Less than 5ppb - Devices requiring no remediation | | | | | | | | | | | |
|---|-----------------------|------------------------|----------|----------------|-----------------|---------------------|---------------|---------------------------|----------------------------------|---------------------------|----------------------------------|
| Record ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
| WS- 010338 | 1/4/2022 | 1/4/2023 | Basement | Food Prep Sink | In kitchen | WF-01042022-010338 | 1/9/2023 | FT-FY23-11182022-010338-A | 1.5 | FT-FY23-11182022-010338-B | 1.6 |

FY23 Filter Test

| Greater than 5ppb - Devices requiring remediation | | | | | | | | | | | |
|---|-----------------------|------------------------|----------|----------------|-----------------------|---------------------|---------------|---------------------------|----------------------------------|---------------------------|----------------------------------|
| Record ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
| WS- 007914 | 5/17/2022 | 5/17/2023 | Basement | Combo Fountain | In lactation room 007 | WF-05172022-007914 | 1/9/2023 | FT-FY23-11182022-007914-A | 6.0 | FT-FY23-11182022-007914-B | <1 |

First Re-test (After Plumbing Check)

FY23 Filter Test

| Less than 5ppb - Devices requiring no remediation | | | | | | | | | | | |
|---|-----------------------|------------------------|----------|----------------|-----------------------|---------------------|---------------|---------------------------|----------------------------------|---------------------------|----------------------------------|
| Record ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
| WS- 007914 | 1/19/2023 | 1/19/2024 | Basement | Combo Fountain | In lactation room 007 | WF-01192023-007914 | 1/27/2023 | FT-FY23-01232023-007914-A | <1 | FT-FY23-01232023-007914-B | <1 |