



ROSS ES LEAD WATER TEST RESULTS



	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)
1	ROSS ELEMENTARY SCHOOL	WS- 010079	8/20/2016	1	Fountain	Exterior, across from play area	FT-72016-010079-A	< 1	FT-72016-010079-B	< 1
2	ROSS ELEMENTARY SCHOOL	WS- 010319	8/20/2016	2	Cooler	In hallway adjacent to room 204 High Left	FT-72016-010319-A	< 1	FT-72016-010319-B	< 1
3	ROSS ELEMENTARY SCHOOL	WS- 010320	8/20/2016	2	Cooler	In hallway adjacent to room 204 Low Right	FT-72016-010320-A	< 1	FT-72016-010320-B	< 1
4	ROSS ELEMENTARY SCHOOL	WS- 010325	8/20/2016	1	Cooler	In hallway adjacent to room 105 High Left	FT-72016-010325-A	< 1	FT-72016-010325-B	< 1
5	ROSS ELEMENTARY SCHOOL	WS- 010326	8/20/2016	1	Cooler	In hallway adjacent to room 105 Low Right	FT-72016-010326-A	< 1	FT-72016-010326-B	< 1
6	ROSS ELEMENTARY SCHOOL	WS- 010331	8/20/2016	Basement	Cooler	In hallway adjacent to main office Low Right	FT-72016-010331-A	< 1	FT-72016-010331-B	< 1
7	ROSS ELEMENTARY SCHOOL	WS- 010332	8/20/2016	Basement	Cooler	In hallway adjacent to main office High Left	FT-72016-010332-A	< 1	FT-72016-010332-B	< 1
8	ROSS ELEMENTARY SCHOOL	WS- 010334	8/20/2016	Basement	Health Suite	In health suite	FT-72016-010334-A	< 1	FT-72016-010334-B	< 1
9	ROSS ELEMENTARY SCHOOL	WS- 010335	8/20/2016	Basement	Cooler	In cafeteria High Left	FT-72016-010335-A	< 1	FT-72016-010335-B	< 1
10	ROSS ELEMENTARY SCHOOL	WS- 010336	8/20/2016	Basement	Cooler	In cafeteria Low Right	FT-72016-010336-A	< 1	FT-72016-010336-B	< 1
11	ROSS ELEMENTARY SCHOOL	WS- 010338	8/20/2016	Basement	Food Prep Sink	In kitchen	FT-72016-010338-A	< 1	FT-72016-010338-B	< 1