



# ROSS LEAD WATER TEST RESULTS

May 24th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010319	Cooler	2	In hallway adjacent to room 204 Left High	WT-042916-10336- A	< 2	WT-042916-10336- B	< 2				
2	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010320	Cooler	2	In hallway adjacent to room 204 Right Low	WT-042916-10337- A	< 2	WT-042916-10337- B	< 2				
3	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010321	Classroom	2	In classroom 204	WT-042916-10338- A	< 2	WT-042916-10338- B	< 2				
4	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010322	Classroom	2	In classroom 207	WT-042916-10339- A	< 2	WT-042916-10339- B	< 2				
5	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010323	Classroom	2	In classroom 205	WT-042916-10340- A	< 2	WT-042916-10340- B	< 2				
6	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010324	Classroom	2	In classroom 202	WT-042916-10341- A	< 2	WT-042916-10341- B	< 2				
7	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010325	Cooler	1	In hallway adjacent to room 105 Left High	WT-042916-10342- A	< 2	WT-042916-10342- B	< 2				
8	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010326	Cooler	1	In hallway adjacent to room 105 Right Low	WT-042916-10343- A	< 2	WT-042916-10343- B	< 2				
9	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010327	Classroom	1	In classroom 105	WT-042916-10344- A	< 2	WT-042916-10344- B	< 2				
10	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010328	Classroom	1	In classroom 106	WT-042916-10345- A	< 2	WT-042916-10345- B	< 2				
11	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010329	Classroom	1	In classroom 109	WT-042916-10346- A	< 2	WT-042916-10346- B	< 2				
12	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010330	Classroom	1	In classroom 102	WT-042916-10347- A	< 2	WT-042916-10347- B	< 2				
13	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010331	Cooler	Basement	In hallway adjacent to main office Right Low	WT-042916-10348- A	< 2	WT-042916-10348- B	< 2				
14	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010332	Cooler	Basement	In hallway adjacent to main office Left Low	WT-042916-10349- A	< 2	WT-042916-10349- B	< 2				
15	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010333	Classroom	Basement	In teachers lounge B06	WT-042916-10350- A	< 2	WT-042916-10350- B	< 2				
16	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010334	Classroom	Basement	In health suite	WT-042916-10351- A	< 2	WT-042916-10351- B	< 2				
17	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010335	Cooler	Basement	In the cafeteria Left High	WT-042916-10352- A	< 2	WT-042916-10352- B	< 2				
18	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010336	Cooler	Basement	In the cafeteria Right Low	WT-042916-10353- A	< 2	WT-042916-10353- B	< 2				
19	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010337	Utility	Basement	In cafeteria (main line in utility closet)	WT-042916-10354- A	< 2	WT-042916-10354- B	< 2				
20	ROSS ELEMENTARY SCHOOL	5/12/2016	WS-010338	Kitchen	Basement	In the kitchen	WT-042916-10355- A	< 2	WT-042916-10355- B	< 2				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.