



ROSS ES LEAD WATER TEST RESULTS



Initial Filter Test After Installation

Less than 1 ppb - Device Returned to Service										
	Building Location: Building Name	Water Source ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	ROSS ELEMENTARY SCHOOL	WS- 010333	12/17/2016	Basement	Break Room	In staff lounge B06	FT-112016-010333-A	< 1	FT-112016-010333-B	< 1
2	ROSS ELEMENTARY SCHOOL	WS- 010330	12/17/2016	1	Classroom Faucet	In classroom 102	FT-122016-010330-A	< 1	FT-122016-010330-B	< 1
3	ROSS ELEMENTARY SCHOOL	WS- 010327	12/17/2016	1	Classroom Faucet	In classroom 105	FT-122016-010327-A	< 1	FT-122016-010327-B	< 1

Greater than 1 ppb - Devices Shut Off and Corrective Action Taken										
1	ROSS ELEMENTARY SCHOOL	WS- 010328	12/17/2016	1	Classroom Faucet	In classroom 106	FT-122016-010328-A	1.7	FT-122016-010328-B	< 1
2	ROSS ELEMENTARY SCHOOL	WS- 010329	12/17/2016	1	Classroom Faucet	In classroom 109	FT-122016-010329-A	1.4	FT-122016-010329-B	< 1

First Filter Re-Test (After Filter and Plumbing Check with Aerator Replacement)

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation										
1	ROSS ELEMENTARY SCHOOL	WS- 010328	1/25/2017	1	Classroom Faucet	In classroom 106	FT-122016-010328-A	1.3	FT-122016-010328-B	< 1
2	ROSS ELEMENTARY SCHOOL	WS- 010329	1/25/2017	1	Classroom Faucet	In classroom 109	FT-122016-010329-A	1.1	FT-122016-010329-B	< 1

Second Filter Re-Test (After Device Replacement)

Less than 1 ppb - Device Returned to Service										
1	ROSS ELEMENTARY SCHOOL	WS- 010328	3/14/2017	1	Classroom Faucet	In classroom 106	FT-122016-010328-A	< 1	FT-122016-010328-B	< 1
2	ROSS ELEMENTARY SCHOOL	WS- 010329	3/14/2017	1	Classroom Faucet	In classroom 109	FT-122016-010329-A	< 1	FT-122016-010329-B	< 1

Note :

Filter re-tests are only performed to devices that have sampling results greater than 1 ppb