



# Ross ES Lead Water Test Results



## FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010097	5/15/2018	5/15/2019	2	Bottle Filler	In hallway adjacent to room 204	WF-05152018-010097	11/3/2018	FT-FY19-102018-010097-A	< 1	FT-FY19-102018-010097-B	< 1
WS- 010098	5/15/2018	5/15/2019	1	Bottle Filler	In hallway adjacent to room 105	WF-05152018-010098	11/3/2018	FT-FY19-102018-010098-A	< 1	FT-FY19-102018-010098-B	< 1
WS- 010099	5/15/2018	5/15/2019	Basement	Bottle Filler	In hallway adjacent to main office	WF-05152018-010099	11/3/2018	FT-FY19-102018-010099-A	< 1	FT-FY19-102018-010099-B	< 1
WS- 010319	5/15/2018	5/15/2019	2	Cooler	In hallway adjacent to room 204 High Left	WF-05152018-010319	11/3/2018	FT-FY19-102018-010319-A	< 1	FT-FY19-102018-010319-B	< 1
WS- 010320	5/15/2018	5/15/2019	2	Cooler	In hallway adjacent to room 204 Low Right	WF-05152018-010320	11/3/2018	FT-FY19-102018-010320-A	< 1	FT-FY19-102018-010320-B	< 1
WS- 010325	5/15/2018	5/15/2019	1	Cooler	In hallway adjacent to room 105 High Left	WF-05152018-010325	11/3/2018	FT-FY19-102018-010325-A	< 1	FT-FY19-102018-010325-B	< 1
WS- 010326	5/15/2018	5/15/2019	1	Cooler	In hallway adjacent to room 105 Low Right	WF-05152018-010326	11/3/2018	FT-FY19-102018-010326-A	< 1	FT-FY19-102018-010326-B	< 1
WS- 010327	9/26/2018	9/26/2019	1	Classroom Faucet	In classroom 105	WF-09262018-010327	11/3/2018	FT-FY19-102018-010327-A	< 1	FT-FY19-102018-010327-B	< 1
WS- 010328	9/26/2018	9/26/2019	1	Classroom Faucet	In classroom 106	WF-09262018-010328	11/3/2018	FT-FY19-102018-010328-A	< 1	FT-FY19-102018-010328-B	< 1
WS- 010329	9/26/2018	9/26/2019	1	Classroom Faucet	In classroom 109	WF-09262018-010329	11/3/2018	FT-FY19-102018-010329-A	< 1	FT-FY19-102018-010329-B	< 1
WS- 010330	9/26/2018	9/26/2019	1	Classroom Faucet	In classroom 102	WF-09262018-010330	11/3/2018	FT-FY19-102018-010330-A	< 1	FT-FY19-102018-010330-B	< 1
WS- 010331	5/15/2018	5/15/2019	Basement	Cooler	In hallway adjacent to main office Low Right	WF-05152018-010331	11/3/2018	FT-FY19-102018-010331-A	< 1	FT-FY19-102018-010331-B	< 1
WS- 010332	5/15/2018	5/15/2019	Basement	Cooler	In hallway adjacent to main office High Left	WF-05152018-010332	11/3/2018	FT-FY19-102018-010332-A	< 1	FT-FY19-102018-010332-B	< 1
WS- 010333	5/15/2018	5/15/2019	Basement	Break Room	In staff lounge B06	WF-05152018-010333	11/3/2018	FT-FY19-102018-010333-A	< 1	FT-FY19-102018-010333-B	< 1
WS- 010334	5/15/2018	5/15/2019	Basement	Health Suite	In health suite	WF-05152018-010334	11/3/2018	FT-FY19-102018-010334-A	< 1	FT-FY19-102018-010334-B	< 1
WS- 010335	5/15/2018	5/15/2019	Basement	Cooler	In cafeteria High Left	WF-05152018-010335	11/3/2018	FT-FY19-102018-010335-A	< 1	FT-FY19-102018-010335-B	< 1
WS- 010336	5/15/2018	5/15/2019	Basement	Cooler	In cafeteria Low Right	WF-05152018-010336	11/3/2018	FT-FY19-102018-010336-A	< 1	FT-FY19-102018-010336-B	< 1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010338	Basement	Food Prep Sink	In kitchen	11/3/2018	FT-FY19-102018-010338-A	< 1	FT-FY19-102018-010338-B	< 1