



RUMSEY AQUATIC LEAD WATER TEST RESULTS May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	RUMSEY AQUATIC CENTER	5/28/2016	WS-005676	Cooler	1	In hallway adjacent to women's restroom Right High	WT-042916-5693- A	< 1	WT-042916-5693- B	< 1				
2	RUMSEY AQUATIC CENTER	5/28/2016	WS-005677	Cooler	1	In hallway adjacent to women's restroom Left Low	WT-042916-5694- A	< 1	WT-042916-5694- B	< 1				
3	RUMSEY AQUATIC CENTER	5/28/2016	WS-005678	Utility	1	In boiler room facing exit to groundfloor (water source)	WT-042916-5695- A	< 1	WT-042916-5695- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.