



GODING ES LEAD WATER TEST RESULTS



Initial Filter Test After Installation

	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	GODING ELEMENTARY SCHOOL	WS- 010584	1/7/2017	3	Classroom Faucet	In classroom 307	FT-112016-010584-A	< 1	FT-112016-010584-B	< 1
2	GODING ELEMENTARY SCHOOL	WS- 008617	1/7/2017	Ground Floor	Classroom Faucet	In classroom 002	FT-112016-008617-A	< 1	FT-112016-008617-B	< 1
3	GODING ELEMENTARY SCHOOL	WS- 010561	1/7/2017	Ground Floor	Classroom Faucet	In classroom 007	FT-112016-010561-A	< 1	FT-112016-010561-B	< 1
4	GODING ELEMENTARY SCHOOL	WS- 010562	1/7/2017	Ground Floor	Classroom Faucet	In classroom 006	FT-112016-010562-A	< 1	FT-112016-010562-B	< 1
5	GODING ELEMENTARY SCHOOL	WS- 008618	1/7/2017	Ground Floor	Classroom Faucet	In classroom 003	FT-112016-008618-A	< 1	FT-112016-008618-B	< 1
6	GODING ELEMENTARY SCHOOL	WS- 010569	1/7/2017	1	Classroom Faucet	In art studio	FT-112016-010569-A	1.7	FT-112016-010569-B	< 1

First Filter Re-Test (After Filter and Plumbing Check with Aerator Replacement)

6	GODING ELEMENTARY SCHOOL	WS- 010569	2/8/2017	1	Classroom Faucet	In art studio	FT-112016-010569-A	11	FT-112016-010569-B	< 1
---	--------------------------	------------	----------	---	------------------	---------------	--------------------	----	--------------------	-----

Note :

Filter re-tests are only performed to devices that have sampling results greater than 1 ppb