



# SCHOOL WITHIN A SCHOOL LEAD WATER TEST RESULTS

May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 008616	Utility	Basement	In boiler room (water source)	WT-042916-8633- A	< 1	WT-042916-8633- B	< 1				
2	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 008617	Classroom	Ground Floor	In classroom 002	WT-042916-8634- A	< 1	WT-042916-8634- B	< 1				
3	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 008618	Classroom	Ground Floor	In classroom 003	WT-042916-8635- A	< 1	WT-042916-8635- B	< 1				
4	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010558	Classroom	Ground Floor	Therapy room adjacent to storage	WT-042916-10575- A	< 1	WT-042916-10575- B	< 1				
5	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010559	Cooler	Ground Floor	In hallway adjacent to custodian closet	WT-042916-10576- A	< 1	WT-042916-10576- B	< 1				
6	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010560	Health Suite	Ground Floor	In health suit	WT-042916-10577- A	< 1	WT-042916-10577- B	1				
7	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010561	Classroom	Ground Floor	In classroom 007	WT-042916-10578- A	1	WT-042916-10578- B	1				
8	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010562	Classroom	Ground Floor	In classroom 006	WT-042916-10579- A	5	WT-042916-10579- B	2				
9	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010563	Cooler	Ground Floor	In gym /cafeteria	WT-042916-10580- A	< 1	WT-042916-10580- B	< 1				
10	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010564	Kitchen	Ground Floor	In kitchen Left	WT-042916-10581- A	< 1	WT-042916-10581- B	< 1				
11	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010565	Kitchen	Ground Floor	In kitchen Right	WT-042916-10582- A	< 1	WT-042916-10582- B	< 1				
14	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010568	Cooler	1	In hallway adjacent to custodian closet	WT-042916-10585- A	< 1	WT-042916-10585- B	< 1				
15	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010569	Classroom	1	In art studio	WT-042916-10586- A	< 1	WT-042916-10586- B	< 1				
16	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010570	Cooler	1	In hallway adjacent to classroom 103	WT-042916-10587- A	< 1	WT-042916-10587- B	< 1				
17	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010571	Classroom	1	In health suite adjacent to principal office	WT-042916-10588- A	2	WT-042916-10588- B	< 1				
18	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010572	Cooler	2	In hallway adjacent to classroom 203	WT-042916-10589- A	1	WT-042916-10589- B	< 1				
19	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010573	Classroom	2	In classroom 203 (art studio)	WT-042916-10590- A	< 1	WT-042916-10590- B	< 1				
20	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010574	Classroom	2	In classroom 206 left 1 Left	WT-042916-10591- A	< 1	WT-042916-10591- B	< 1				
21	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010575	Classroom	2	In classroom 206 middle 2 Mid	WT-042916-10592- A	< 1	WT-042916-10592- B	< 1				
22	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010576	Classroom	2	In classroom 206 middle 3 Mid	WT-042916-10593- A	< 1	WT-042916-10593- B	< 1				
23	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010577	Classroom	2	In classroom 206 right 4 Right	WT-042916-10594- A	1	WT-042916-10594- B	< 1				
24	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010578	Classroom	2	In classroom 206 right 5 Right	WT-042916-10595- A	< 1	WT-042916-10595- B	< 1				
25	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010579	Classroom	2	In classroom 206 right 6 Right	WT-042916-10596- A	< 1	WT-042916-10596- B	< 1				
26	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010580	Classroom	2	In classroom 206 right 7 Right	WT-042916-10597- A	< 1	WT-042916-10597- B	< 1				
27	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010581	Cooler	2	In hallway adjacent to custodians closet	WT-042916-10598- A	< 1	WT-042916-10598- B	< 1				
28	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010582	Classroom	2	In classroom 206 A Right	WT-042916-10599- A	3	WT-042916-10599- B	< 1				
29	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010583	Classroom	2	In classroom 206A Left	WT-042916-10600- A	< 1	WT-042916-10600- B	< 1				
30	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010584	Classroom	3	In classroom 307	WT-042916-10601- A	< 1	WT-042916-10601- B	< 1				
31	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010585	Classroom	3	In classroom (library)	WT-042916-10602- A	1	WT-042916-10602- B	< 1				
32	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010586	Cooler	3	In hallway adjacent to custodian closet	WT-042916-10603- A	< 1	WT-042916-10603- B	< 1				
33	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010587	Cooler	3	In hallway adjacent to classroom 303	WT-042916-10604- A	< 1	WT-042916-10604- B	< 1				



## SCHOOL WITHIN A SCHOOL LEAD WATER TEST RESULTS

May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
34	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010588	Classroom	4	In classroom 407	WT-042916-10605- A	2	WT-042916-10605- B	1				
35	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010589	Cooler	4	In hallway adjacent to teachers restroom	WT-042916-10606- A	< 1	WT-042916-10606- B	< 1				
36	SCHOOL WITHIN A SCHOOL	5/12/2016	WS- 010590	Cooler	4	In hallway adjacent to classroom 403	WT-042916-10607- A	< 1	WT-042916-10607- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.