



SCHOOL WITHOUT WALLS HIGH SCHOOL LEAD WATER TEST RESULTS May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012080	Utility	Basement	In men's bathroom adjacent to room 21 (Main water source)	WT-042916-12097- A	< 1	WT-042916-12097- B	< 1				
2 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012081	Cooler	3	In hallway adjacent to elevator Left High	WT-042916-12098- A	< 1	WT-042916-12098- B	< 1				
3 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012082	Cooler	3	In hallway adjacent to elevator Right Low	WT-042916-12099- A	< 1	WT-042916-12099- B	< 1				
4 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012083	Classroom	3	In room 301	WT-042916-12100- A	< 1	WT-042916-12100- B	< 1				
5 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012084	Break Room	3	In break room	WT-042916-12101- A	< 1	WT-042916-12101- B	< 1				
6 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012085	Other	3	In break room (ice maker)	WT-042916-12102- A	< 1	WT-042916-12102- B	< 1				
7 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012086	Cooler	2	In hallway adjacent to elevator Left High	WT-042916-12103- A	< 1	WT-042916-12103- B	< 1				
8 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012087	Cooler	2	In hallway adjacent to elevator Right Low	WT-042916-12104- A	< 1	WT-042916-12104- B	< 1				
9 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012088	Cooler	1	In hallway adjacent to elevator Left High	WT-042916-12105- A	< 1	WT-042916-12105- B	< 1				
10 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012089	Cooler	1	In hallway adjacent to elevator Right Low	WT-042916-12106- A	< 1	WT-042916-12106- B	< 1				
11 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012090	Kitchen	1	In kitchen	WT-042916-12107- A	< 1	WT-042916-12107- B	< 1				
12 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012091	Health Suite	1	In health suite	WT-042916-12108- A	< 1	WT-042916-12108- B	< 1				
13 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012092	Other	1	In health suite (ice maker)	WT-042916-12109- A	< 1	WT-042916-12109- B	< 1				
14 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012093	Classroom	Basement	In room 14 first sink clockwise from entry door Left	WT-042916-12110- A	1.4	WT-042916-12110- B	< 1				
15 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012094	Classroom	Basement	In room 14 first sink clockwise from entry door Right	WT-042916-12111- A	1.5	WT-042916-12111- B	< 1				
16 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012095	Classroom	Basement	In room 14 second sink clockwise from entry door Left	WT-042916-12112- A	6.9	WT-042916-12112- B	4				
17 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012096	Classroom	Basement	In room 14 second sink clockwise from entry door Right	WT-042916-12113- A	3.1	WT-042916-12113- B	1.4				
18 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012097	Classroom	Basement	In room 14 third sink clockwise from entry door Left	WT-042916-12114- A	6.2	WT-042916-12114- B	1.1				
19 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012098	Classroom	1	In room 14 third sink clockwise from entry door Right	WT-042916-12115- A	5.1	WT-042916-12115- B	1.1				
20 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012099	Classroom	Basement	In room 14 fourth sink clockwise from entry door Right	WT-042916-12116- A	3.9	WT-042916-12116- B	< 1				
21 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012100	Classroom	Basement	In room 14 fourth sink clockwise from entry door Left	WT-042916-12117- A	6	WT-042916-12117- B	< 1				
22 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012101	Classroom	1	In room 14 fifth sink clockwise from entry door Right	WT-042916-12118- A	2.1	WT-042916-12118- B	< 1				
23 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012102	Classroom	Basement	In room 14 fifth sink clockwise from entry door Left	WT-042916-12119- A	2.8	WT-042916-12119- B	< 1				
24 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012103	Classroom	Basement	In room 14 sixth sink clockwise from entry door Right	WT-042916-12120- A	4.8	WT-042916-12120- B	1.5				
25 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012104	Classroom	Basement	In room 14 sixth sink clockwise from entry door Left	WT-042916-12121- A	4.6	WT-042916-12121- B	< 1				
26 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012105	Classroom	Basement	In room 14 seventh sink clockwise from entry door	WT-042916-12122- A	12	WT-042916-12122- B	< 1				
27 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012106	Classroom	Basement	In room 13 first sink clockwise from entry door	WT-042916-12123- A	1.8	WT-042916-12123- B	< 1				
28 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012107	Classroom	Basement	In room 13 second sink clockwise from entry door	WT-042916-12124- A	9.4	WT-042916-12124- B	1.5				
29 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012108	Classroom	Basement	In room 13 third sink clockwise from entry door	WT-042916-12125- A	2.7	WT-042916-12125- B	< 1				
30 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012109	Classroom	Basement	In room 12 first sink clockwise from entry door Left	WT-042916-12126- A	2.8	WT-042916-12126- B	< 1				
31 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012110	Classroom	Basement	In room 12 first sink clockwise from entry door Right	WT-042916-12127- A	< 1	WT-042916-12127- B	< 1				
32 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012111	Classroom	Basement	In room 12 second sink clockwise from entry door Left	WT-042916-12128- A	5.4	WT-042916-12128- B	< 1				
33 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012112	Classroom	Basement	In room 12 second sink clockwise from entry door Right	WT-042916-12129- A	< 1	WT-042916-12129- B	< 1				
34 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012113	Classroom	Basement	In room 12 third sink clockwise from entry door Left	WT-042916-12130- A	7.4	WT-042916-12130- B	< 1				
35 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012114	Classroom	Basement	In room 12 fourth sink clockwise from entry door Left	WT-042916-12131- A	3.4	WT-042916-12131- B	< 1				
36 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012115	Classroom	Basement	In room 12 third sink clockwise from entry door Right	WT-042916-12132- A	1.4	WT-042916-12132- B	< 1				
37 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012116	Classroom	Basement	In room 12 fourth sink clockwise from entry door Right	WT-042916-12133- A	1.1	WT-042916-12133- B	< 1				
38 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012117	Classroom	Basement	In room 12 fifth sink clockwise from entry door Left	WT-042916-12134- A	2.9	WT-042916-12134- B	< 1				



SCHOOL WITHOUT WALLS HIGH SCHOOL LEAD WATER TEST RESULTS May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
39 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012118	Classroom	Basement	In room 12 fifth sink clockwise from entry door Right	WT-042916-12135- A	1.4	WT-042916-12135- B	< 1				
40 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012119	Classroom	Basement	In room 12 sixth sink clockwise from entry door Left	WT-042916-12136- A	5.8	WT-042916-12136- B	< 1				
41 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012120	Classroom	Basement	In room 12 sixth sink clockwise from entry door Right	WT-042916-12137- A	6.3	WT-042916-12137- B	< 1				
42 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012121	Classroom	Basement	In room 12 seventh sink clockwise from entry door	WT-042916-12138- A	< 1	WT-042916-12138- B	< 1				
43 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012122	Classroom	Basement	In room 11 first sink clockwise from entry door Left	WT-042916-12139- A	4.2	WT-042916-12139- B	< 1				
44 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012123	Classroom	Basement	In room 11 first sink clockwise from entry door Right	WT-042916-12140- A	< 1	WT-042916-12140- B	< 1				
45 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012124	Classroom	Basement	In room 11 second sink clockwise from entry door Left	WT-042916-12141- A	1.6	WT-042916-12141- B	< 1				
46 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012125	Classroom	Basement	In room 11 second sink clockwise from entry door Right	WT-042916-12142- A	< 1	WT-042916-12142- B	< 1				
47 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012126	Classroom	Basement	In room 11 third sink clockwise from entry door Left	WT-042916-12143- A	10	WT-042916-12143- B	< 1				
48 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012127	Classroom	Basement	In room 11 third sink clockwise from entry door Right	WT-042916-12144- A	< 1	WT-042916-12144- B	< 1				
49 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012128	Classroom	Basement	In room 11 fourth sink clockwise from entry door Left	WT-042916-12145- A	< 1	WT-042916-12145- B	< 1				
50 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012129	Classroom	Basement	In room 11 fourth sink clockwise from entry door Right	WT-042916-12146- A	1.6	WT-042916-12146- B	< 1				
51 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012130	Classroom	Basement	In room 11 fifth sink clockwise from entry door Left	WT-042916-12147- A	< 1	WT-042916-12147- B	< 1				
52 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012131	Classroom	Basement	In room 11 fifth sink clockwise from entry door Right	WT-042916-12148- A	4.5	WT-042916-12148- B	< 1				
53 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012132	Classroom	Basement	In room 11 sixth sink clockwise from entry door Left	WT-042916-12149- A	< 1	WT-042916-12149- B	< 1				
54 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012133	Classroom	Basement	In room 11 sixth sink clockwise from entry door Right	WT-042916-12150- A	1.6	WT-042916-12150- B	< 1				
55 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012134	Classroom	Basement	In room 11 seventh sink clockwise from entry door	WT-042916-12151- A	< 1	WT-042916-12151- B	< 1				
56 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012135	Classroom	Basement	In room 11a	WT-042916-12152- A	34	WT-042916-12152- B	3.4	Filter will be installed and then retested			
57 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012136	Cooler	Basement	In hallway adjacent to elevator Left High	WT-042916-12153- A	< 1	WT-042916-12153- B	< 1				
58 SCHOOL WITHOUT WALLS HIGH SCHOOL	5/18/2016	WS- 012137	Cooler	Basement	In hallway adjacent to elevator Right Low	WT-042916-12154- A	< 1	WT-042916-12154- B	< 1				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.