



School w/out Walls High School Lead in Water Test Results

FY25 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012081	4/18/2024	4/18/2025	3	Cooler	In hallway adjacent to elevator High Left	WF-04182024-012081	10/26/2024	FT-FY25-10082024-012081-A	<2	FT-FY25-10082024-012081-B	<2
WS- 012082	4/18/2024	4/18/2025	3	Cooler	In hallway adjacent to elevator Low Right	WF-04182024-012082	10/26/2024	FT-FY25-10082024-012082-A	<2	FT-FY25-10082024-012082-B	<2
WS- 012084	4/18/2024	4/18/2025	3	Break Room	In break room	WF-04182024-012084	10/26/2024	FT-FY25-10082024-012084-A	<2	FT-FY25-10082024-012084-B	<2
WS- 012086	4/18/2024	4/18/2025	2	Cooler	In hallway adjacent to elevator High Left	WF-04182024-012086	10/26/2024	FT-FY25-10082024-012086-A	<2	FT-FY25-10082024-012086-B	<2
WS- 012087	4/18/2024	4/18/2025	2	Cooler	In hallway adjacent to elevator Low Right	WF-04182024-012087	10/26/2024	FT-FY25-10082024-012087-A	<2	FT-FY25-10082024-012087-B	<2
WS- 012088	4/18/2024	4/18/2025	1	Cooler	In hallway adjacent to elevator High Left	WF-04182024-012088	10/26/2024	FT-FY25-10082024-012088-A	<2	FT-FY25-10082024-012088-B	<2
WS- 012089	4/18/2024	4/18/2025	1	Cooler	In hallway adjacent to elevator Low Right	WF-04182024-012089	10/26/2024	FT-FY25-10082024-012089-A	<2	FT-FY25-10082024-012089-B	<2
WS- 012091	4/18/2024	4/18/2025	1	Health Suite	In health suite	WF-04182024-012091	10/26/2024	FT-FY25-10082024-012091-A	<2	FT-FY25-10082024-012091-B	<2
WS- 012136	4/18/2024	4/18/2025	Basement	Cooler	In hallway adjacent to elevator High Left	WF-04182024-012136	10/26/2024	FT-FY25-10082024-012136-A	<2	FT-FY25-10082024-012136-B	<2
WS- 012137	4/18/2024	4/18/2025	Basement	Cooler	In hallway adjacent to elevator Low Right	WF-04182024-012137	10/26/2024	FT-FY25-10082024-012137-A	<2	FT-FY25-10082024-012137-B	<2
WS- 012141	4/18/2024	4/18/2025	3	Bottle Filler	In hallway adjacent to elevator	WF-04182024-012141	10/26/2024	FT-FY25-10082024-012141-A	<2	FT-FY25-10082024-012141-B	<2
WS- 012142	4/18/2024	4/18/2025	2	Bottle Filler	In hallway adjacent to elevator	WF-04182024-012142	10/26/2024	FT-FY25-10082024-012142-A	<2	FT-FY25-10082024-012142-B	<2
WS- 012143	4/18/2024	4/18/2025	1	Bottle Filler	In hallway adjacent to elevator	WF-04182024-012143	10/26/2024	FT-FY25-10082024-012143-A	<2	FT-FY25-10082024-012143-B	<2

Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012090	11/29/2023	11/29/2024	1	Food Prep Sink	In kitchen	WF-11292023-012090	10/26/2024	FT-FY25-10082024-012090-A	<2	FT-FY25-10082024-012090-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.