

## Shepherd Park Community Center Lead in Water Test Results

FY23 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 004851	3/16/2022	3/16/2023	1	Bottle Filler	In hallway between restrooms	WF-03162022-004851	2/17/2023	FT-FY23-01192023-004851-A	<1	FT-FY23-01192023-004851-B	<1
WS- 004852	3/16/2022	3/16/2023	1	Cooler	In hallway between restrooms High Left	WF-03162022-004852	2/17/2023	FT-FY23-01192023-004852-A	<1	FT-FY23-01192023-004852-B	<1
WS- 004853	3/16/2022	3/16/2023	1	Cooler	In hallway between restrooms Low Right	WF-03162022-004853	2/17/2023	FT-FY23-01192023-004853-A	<1	FT-FY23-01192023-004853-B	<1
WS- 004854	3/16/2022	3/16/2023	1	Food Prep Sink	In kitchenette 107	WF-03162022-004854	2/17/2023	FT-FY23-01192023-004854-A	<1	FT-FY23-01192023-004854-B	<1