



# Shepherd Park Community Center Lead in Water Test Results

## FY24 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 004851	3/1/2024	3/1/2025	1	Bottle Filler	In hallway between restrooms	WF-03012024-004851	3/18/2024	FT-FY24-03052024-004851-A	<1	FT-FY24-03052024-004851-B	<1
WS- 004852	3/1/2024	3/1/2025	1	Cooler	In hallway between restrooms High Left	WF-03012024-004852	3/18/2024	FT-FY24-03052024-004852-A	<1	FT-FY24-03052024-004852-B	<1
WS- 004853	3/1/2024	3/1/2025	1	Cooler	In hallway between restrooms Low Right	WF-03012024-004853	3/18/2024	FT-FY24-03052024-004853-A	<1	FT-FY24-03052024-004853-B	<1
WS- 004854	12/27/2023	12/27/2024	1	Food Prep Sink	In kitchenette 107	WF-12272023-004854	3/18/2024	FT-FY24-03052024-004854-A	<1	FT-FY24-03052024-004854-B	<1