



Sherwood RC Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005781	4/17/2018	4/17/2019	1	Cooler	In hallway adjacent to restrooms High Left	WF-04172018-005781	3/4/2019	FT-FY19-022019-005781-A	<1	FT-FY19-022019-005781-B	<1
WS- 005782	4/17/2018	4/17/2019	1	Cooler	In hallway adjacent to restrooms Low Right	WF-04172018-005782	3/4/2019	FT-FY19-022019-005782-A	<1	FT-FY19-022019-005782-B	<1
WS- 005783	4/17/2018	4/17/2019	2	Cooler	In hallway adjacent to restrooms High Left	WF-04172018-005783	3/4/2019	FT-FY19-022019-005783-A	<1	FT-FY19-022019-005783-B	<1
WS- 005784	4/17/2018	4/17/2019	2	Cooler	In hallway adjacent to restrooms Low Right	WF-04172018-005784	3/4/2019	FT-FY19-022019-005784-A	<1	FT-FY19-022019-005784-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005785	4/17/2018	4/17/2019	2	Food Prep Sink	In pantry room 206	WF-04172018-005785	3/4/2019	FT-FY19-022019-005785-A	<1	FT-FY19-022019-005785-B	<1