



# SHERWOOD REC LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 SHERWOOD RECREATION CENTER	5/21/2016	WS-005781	Cooler	1	In hallway adjacent to restrooms Left High	WT-042916-5798-A	< 1	WT-042916-5798-B	< 1				
2 SHERWOOD RECREATION CENTER	5/21/2016	WS-005782	Cooler	1	In hallway adjacent to restrooms Right Low	WT-042916-5799-A	< 1	WT-042916-5799-B	< 1				
3 SHERWOOD RECREATION CENTER	5/21/2016	WS-005783	Cooler	2	In hallway adjacent to restrooms Left High	WT-042916-5800-A	< 1	WT-042916-5800-B	< 1				
4 SHERWOOD RECREATION CENTER	5/21/2016	WS-005784	Cooler	2	In hallway adjacent to restrooms Right Low	WT-042916-5801-A	< 1	WT-042916-5801-B	< 1				
5 SHERWOOD RECREATION CENTER	5/21/2016	WS-005785	Kitchen	2	In pantry 206	WT-042916-5802-A	< 1	WT-042916-5802-B	< 1				
6 SHERWOOD RECREATION CENTER	5/21/2016	WS-005786	Utility	1	In sprinkler room (water source)	WT-042916-5803-A	190	WT-042916-5803-B	< 1	Non-drinking water source - Not accessible to children			
7 SHERWOOD RECREATION CENTER	5/21/2016	WS-005787	Fountain	Ground Floor	Exterior adjacent to play area Right Low	WT-042916-5804-A	< 1	WT-042916-5804-B	< 1				
8 SHERWOOD RECREATION CENTER	5/21/2016	WS-005788	Fountain	Ground Floor	Exterior adjacent to play area Left High	WT-042916-5805-A	< 1	WT-042916-5805-B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.