



Smothers ES Lead in Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 001600	3/19/2019	3/19/2020	3	Cooler	In hallway adjacent to room 310	WF-03192019-001600	11/20/2019	FT-FY20-112019-001600-A	<1	FT-FY20-112019-001600-B	<1
WS- 001601	3/19/2019	3/19/2020	3	Break Room	In break room	WF-03192019-001601	11/20/2019	FT-FY20-112019-001601-A	<1	FT-FY20-112019-001601-B	<1
WS- 001602	3/19/2019	3/19/2020	3	Cooler	In hallway adjacent to room 301	WF-03192019-001602	11/20/2019	FT-FY20-112019-001602-A	<1	FT-FY20-112019-001602-B	<1
WS- 001603	10/8/2019	10/8/2020	2	Health Suite	In health suite in restroom	WF-10082019-001603	11/20/2019	FT-FY20-112019-001603-A	2.6	FT-FY20-112019-001603-B	<1
WS- 001604	3/19/2019	3/19/2020	2	Cooler	In hallway adjacent to room 201	WF-03192019-001604	11/20/2019	FT-FY20-112019-001604-A	<1	FT-FY20-112019-001604-B	<1
WS- 001605	3/19/2019	3/19/2020	2	Cooler	In hallway adjacent to room 212	WF-03192019-001605	11/20/2019	FT-FY20-112019-001605-A	<1	FT-FY20-112019-001605-B	<1
WS- 001606	3/19/2019	3/19/2020	1	Cooler	In hallway adjacent to room 108	WF-03192019-001606	11/20/2019	FT-FY20-112019-001606-A	<1	FT-FY20-112019-001606-B	<1
WS- 001610	10/8/2019	10/8/2020	1	Bathroom	In classroom 102 in bathroom	WF-10082019-001610	11/20/2019	FT-FY20-112019-001610-A	<1	FT-FY20-112019-001610-B	<1
WS- 001611	10/8/2019	10/8/2020	1	Bathroom	In classroom 104 in bathroom	WF-10082019-001611	11/20/2019	FT-FY20-112019-001611-A	<1	FT-FY20-112019-001611-B	<1
WS- 001612	10/8/2019	10/8/2020	1	Bathroom	In classroom 108 in bathroom	WF-10082019-001612	11/20/2019	FT-FY20-112019-001612-A	1.4	FT-FY20-112019-001612-B	<1
WS- 001613	3/19/2019	3/19/2020	1	Cooler	In hallway adjacent to room 104	WF-03192019-001613	11/20/2019	FT-FY20-112019-001613-A	<1	FT-FY20-112019-001613-B	<1
WS- 001614	10/8/2019	10/8/2020	1	Bathroom	In classroom 110 in bathroom	WF-10082019-001614	11/20/2019	FT-FY20-112019-001614-A	<1	FT-FY20-112019-001614-B	<1
WS- 001615	10/8/2019	10/8/2020	1	Bathroom	In classroom 111 in bathroom	WF-10082019-001615	11/20/2019	FT-FY20-112019-001615-A	<1	FT-FY20-112019-001615-B	<1
WS- 001616	10/8/2019	10/8/2020	1	Bathroom	In classroom 113 in bathroom	WF-10082019-001616	11/20/2019	FT-FY20-112019-001616-A	<1	FT-FY20-112019-001616-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 001609	7/2/2019	7/2/2020	1	Food Prep Sink	In kitchen third clockwise from entry door	WF-07022019-001609	11/20/2019	FT-FY20-112019-001609-A	<1	FT-FY20-112019-001609-B	<1