



# SMOTHERS ES LEAD WATER TEST RESULTS



	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)
1	SMOTHERS ELEMENTARY SCHOOL	WS- 001600	8/16/2016	3	Cooler	In hallway adjacent to room 310	FT-72016-001600-A	< 1	FT-72016-001600-B	< 1
2	SMOTHERS ELEMENTARY SCHOOL	WS- 001602	8/16/2016	3	Cooler	In hallway adjacent to room 301	FT-72016-001602-A	< 1	FT-72016-001602-B	< 1
3	SMOTHERS ELEMENTARY SCHOOL	WS- 001603	8/16/2016	2	Health Suite	In restroom in health suite	FT-72016-001603-A	< 1	FT-72016-001603-B	1.1
4	SMOTHERS ELEMENTARY SCHOOL	WS- 001604	8/16/2016	2	Cooler	In hallway adjacent to room 201	FT-72016-001604-A	< 1	FT-72016-001604-B	< 1
5	SMOTHERS ELEMENTARY SCHOOL	WS- 001605	8/16/2016	2	Cooler	In hallway adjacent to room 212	FT-72016-001605-A	1	FT-72016-001605-B	< 1
6	SMOTHERS ELEMENTARY SCHOOL	WS- 001606	8/16/2016	1	Cooler	in hallway adjacent to room 108	FT-72016-001606-A	< 1	FT-72016-001606-B	< 1
7	SMOTHERS ELEMENTARY SCHOOL	WS- 001609	8/16/2016	1	Food Prep Sink	In kitchen third clockwise from entry door	FT-72016-001609-A	< 1	FT-72016-001609-B	< 1
8	SMOTHERS ELEMENTARY SCHOOL	WS- 001613	8/16/2016	1	Cooler	in hallway adjacent to room 104	FT-72016-001613-A	< 1	FT-72016-001613-B	< 1