



# SMOTHERS ES LEAD WATER TEST RESULTS



## Initial Filter Test After Installation

	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	SMOTHERS ELEMENTARY SCHOOL	WS- 001601	1/6/2017	3	Break Room	In break room	FT-102016-001601-A	< 1	FT-102016-001601-B	< 1
2	SMOTHERS ELEMENTARY SCHOOL	WS- 001611	1/6/2017	1	Bathroom	In classroom 104 in bathroom	FT-112016-001611-A	< 1	FT-112016-001611-B	< 1
3	SMOTHERS ELEMENTARY SCHOOL	WS- 001616	1/6/2017	1	Bathroom	In classroom 113 in bathroom	FT-112016-001616-A	< 1	FT-112016-001616-B	< 1
4	SMOTHERS ELEMENTARY SCHOOL	WS- 001615	1/6/2017	1	Bathroom	In classroom 111 in bathroom	FT-112016-001615-A	< 1	FT-112016-001615-B	< 1
5	SMOTHERS ELEMENTARY SCHOOL	WS- 001614	1/6/2017	1	Bathroom	In classroom 110 in bathroom	FT-112016-001614-A	< 1	FT-112016-001614-B	< 1
6	SMOTHERS ELEMENTARY SCHOOL	WS- 001610	1/6/2017	1	Bathroom	In classroom 102 in bathroom	FT-112016-001610-A	< 1	FT-112016-001610-B	< 1
7	SMOTHERS ELEMENTARY SCHOOL	WS- 001612	1/6/2017	1	Bathroom	In classroom 108 in bathroom	FT-112016-001612-A	< 1	FT-112016-001612-B	< 1

**Note :**

Filter re-tests are only performed to devices that have sampling results greater than 1 ppb